

					ENGINEERING		
			5482823		Cor	nfortDelGro Engineering Pte Ltd	
Date : 1		:18/	08/2021		59 Loyang Drive Singapore 508969 Fax: 6546 8156		
FINALIZATION FORM							
To	:LKK				Fax:		
Attn	4	TAUFIKH					
		SHA	6998G	_	DOA	: 14/08/2021	
The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-							
1.	. The repair job shall bill to:			NTUC		FBH287Z	
2.	The finalized amount shall be:						
	(a) Spare Parts after List discount						
	(b)	Labour Charges	3	##	#	37	
		Total for Part-l	By-Part Repair Cost	:		5:	
	N						
	(c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: 20% \$1,300.00 Final Lumpsum Repair cost						
	- mai Lumpsum Repuir cost						
2	Fetimated normal period for repairs: 2 working days						
3.	Estimated normal period for repairs: working days						
4.	We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days						
5.	Thank you for your assistance.			We confirm the estimates and finalized amount			
	Mr.						
Signature :			MA			taufikh	
	Name : JUMANI			Name		TAUFIKH	
	Tel : 6214 8315			_ Da	Date : 20/8/21		
Fax : 65468156 -							
For Official Use Only							
	Item		Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks	
1 Re	Rental Rate P/Day			YES			
		ncome Paid	X ero	NO			
3. Survey Fees			D XIO				
4. LTA Search Fee			\$7.49 -\$2.00				
5. Me	edical F driver,	ees (on behalf if applicable)					
	errun						
Remarks:							