

REF: CS/LAW21008659/Dtf3

Special Instruction:

L/SUM : \$ 57,014.71

Third Parties:

Claimant:

Surveyor:

Workshop: TEAM AUTOPRO PTE LTD

ASSIGNMENT (Office)

From (Person): TEO YI XUAN of LAW Date/Time: 18/8/2021 12:36 PM
Estimated Cost: _____ Bill to: _____

OD TP Re-inspection / Evaluation

To Inspect Vehicle No: SKL 8223C Insured: XD 8817C
at Workshop m/s TEAM AUTOPRO PTE LTD Tel: 62581955
of 160 SIN MING DR #01-14 SIN MING AUTO CITY

Policy No: GS/20/4184/TAP/jp/cl Claim No: CMTD2001923

Sum Insured: _____ Excess: _____

Make of Veh: _____
(Client's Record) _____ D.O.A. 26/06/2020

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT _____

Date/Time: 20/11 Confirmed with 0000 Final Fig 0000, 00 days (Red \$ 00 / 00 %; Original 20 days)

Date/Time: 30/11 Submit Final Fig 29600, 15 days (Red \$ / 48 %; Original 20 days)
lump sum 27414.71

[illegible]

Para(1) : Parts found not replaced (To highlight *R* or *UB*, *LR*, *Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	
---	--

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add

Transport

Photos

Others

Total

Date: _____

Date/Time		File Pass to		File Return to		Total
1)	Date/Time		File Pass to	2)	Date/Time	File Return to
3)	Date/Time		File Pass to	4)	Date/Time	File Return to
5)	Date/Time		File Pass to	6)	Date/Time	File Return to