

Customer

Vehicle ident no.

Repair order no.
R000004

Technician

Date
25.8.21

License plate no.
SKL7829L

First reg. date

Model
HONDA ODYSSEY YM 2015 (RC1)

Odometer reading: km/miles

Complaints or reason for alignment check

		Before	Target Data	Actual	
Rear axle	Camber	left	-1°32'	-1°32'	
		right	-1°57'	-1°56'	
		cross	0°25'	0°00'	0°25'
	Toe	left	0°13'	0°05' +/-0°05'	0°15'
		right	-0°02'		-0°01'
		total	0°11'	0°09' +/-0°09'	0°13'
Geometrical driving axis		0°08'	0°00'	0°08'	
Front axle	Camber	left	-0°23'	-0°23'	
		right	-0°09'	-0°15'	
		cross	-0°15'	0°00'	-0°09'
	Caster	left	5°06'	5°36' +/-0°45'	5°06'
		right	5°31'		5°31'
		cross	-0°25'	0°00'	-0°25'
	SAI	left	12°43'		12°43'
		right	12°29'		12°35'
		cross	0°14'	0°00'	0°08'
	Track differential angle				
	Toe	left	0°04'	0°00' +/-0°05'	0°03'
		right	-0°16'		-0°01'
total		-0°12'	0°00' +/-0°09'	0°02'	
Setback			0°00'		
Max steering lock	left steer	left			
		right			
	right steer	left			
		right			