

Our Job Ref No 305483049Date : 18/08/2021ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**To : LKK

Fax :

Attn : TAUFIKH: SHA3394TDOA: 16/08/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- GBC2367P


2. The finalized amount shall be:

(a) Spare Parts after List discount \$2,524.32(b) Labour Charges ### \$1,085.00**Total for Part-By-Part Repair Cost** \$3,609.32

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%**Final Lumpsum Repair cost**3. Estimated normal period for repairs: 3 working days4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : Name : JUMANITel : 6214 8315Fax : 65468156Signature : taufikhName : TAUFIKHDate : 31/8/21**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	NO		
3. Survey Fees	---			
4. LTA Search Fee	\$7.49 - \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305483049
 REGN NO : SHA3394T
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 14.11.2019
 DATE/TIME IN : 16.08.2021 16:10
 ACCIDENT DATE : 16.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0578-G	COVER-FR BUMPER#	1	430.90	20.00	344.72
0002 04-01-0104-0574-G	PANEL-FENDER LH#	1	588.80	20.00	471.04
0003 04-01-0104-2835-G	LAMP ASSY-HEAD LH#	1	1,993.65	20.00	1,594.92
0004 04-01-0104-2685-G	MOULDING-FRONT BUMPER LH	1	93.45	20.00	74.76
0005 04-01-0104-3813-G	EMBLEM-BLUE DRIVE LH	1	26.60	20.00	21.28
0006 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60

SUB-TOTAL : 2,524.32

JOB NATURE

0000 PB	PANEL BEATING	525.00
0001 SP	SPRAYPAINT CHARGE	500.00
0002 17-01	CHECK ALL LIGHTING	30.00
0003 20-00	TUFF COAT ON AFFECTED PARTS.	30.00

SUB-TOTAL : 1,085.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305483049
REGN NO : SHA3394T
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 14.11.2019
DATE/TIME IN : 16.08.2021 16:1
ACCIDENT DATE : 16.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,609.32

Jumani

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE
DATE :

SUPPLEMENTARY OF PARTS AND LABOUR COSTS			
DESCRIPTION	QTY	ESTIMATE	REMARKS
MOULDING – FRT BUMPER LH (DAY LIGHT LAMP GRILLE)	1	\$93.45	LIST bro ✓
CHECK ITEMS.			
LABOUR			
TOTAL:		\$93.45	JUMANI