


**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 QD:  TP /  S / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s: **AB ENGINEERING**  
 of \_\_\_\_\_  
 Insured: **SMP 6905L**  
 Policy No: **DMPCSNW00117302000**  
 Claims No: **SNM21D204554/C02/LEEPG**  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**



Bal. or Market Value: **\$79k**  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: **3** days Res.: Yes or No  
 Lum Sum: **20** % 3 Val.: Yes or No  
**CA / REV / REP. / 24 HRS**  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: **GBK 7080R** Yr Regn: **29 Oct 2020**  
 Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: **TOYOTA HIACE DX 2.8** c.c. **2754**  
 Colour: **White** A/C: **Insured / Std / NI / NA**  
 Sp. Reading: **29173** T/Radio: **Insured / Std / NI / NA**  
 Eng/No: \_\_\_\_\_  
 C/No: **GDH2011047702**  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake:  Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi:  Nil / R/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: **195R15**  
 R: **195R15**  
**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /**  
**TOYO / YOKO** or **APLUS**  

<u>Front</u>		<u>Rear</u>	
R/Bal. <b>6</b> mm		R/Bal. <b>6</b> mm	
L/Bal. <b>6</b> mm		L/Bal. <b>6</b> mm	
D.O.A. <b>16/8/21</b>		D.O.I. <b>18-08-2021</b>	

 Survey held at **W/S** **4PM**  
 Des. of Damages: Frt  Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
31/8/21	LS \$2200 confirmed by email (Red 1870.85,45%)

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair: **3**  
 Resurvey No. of Trip: **2**

1) \_\_\_\_\_  
 Date/Time, File Return to?  
 2) **1/9/21-Typist**

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : W/Weekend (\$ \_\_\_\_\_)

Survey Fee:	
Transportation:	
3 + RS. SI	
Photos	
Other:	
TOTAL	

Report Filed by: **Merimen**  
 Lump Sum / MPB: **LS \$2200**