Surveyor:

REF: CS/LAW21008686/Duf3

Special Instruction:

L/SUM : $ 7500.00

Third Parties:

Claimant:

Surveyor:

Workshop: Twincar Automotive Pte Ltd

ASSIGNMENT (Office)

From (Person): TEO YI XUAN of LAW Date/Time: 18/8/2021 8:58 PM

Estimated Cost: Bill to:

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SJU 3505L Insured: SJE 4623G

at Workshop m/s Twincar Automotive Pte Ltd Tel: 6744 0510

of 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921

Policy No: VL:T140.111787.19 Claim No: KC:2020001680.ECICS

Sum Insured: Excess:

Make of Veh: D.O.A. 08/10/2019

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle **IN / OUT**

Date/Time: **Confirmed with** **Final Fig** , days (Red $ / %; Original 8 days)

Date/Time: 30/9/2021 **Submit Final Fig** $2750 , 4 **days** (Red $ 4750 / 63 %; Original days)

Date/Time	Action/Instruction
	SJU 3505L-NA/INC19017774/z4 DOA : 08/10/2019
	SJE 4623G-NA/INC19017774/z4 DOA : 08/10/2019

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : *NC*)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/ Evaluated by:

Fee Charged:	*Date:*
Basic & Add	
Transport	
Photos	
Others	
Total	

1) Date/Time File Pass to 2) Date/Time File Return to

3) Date/Time File Pass to 4) Date/Time File Return to

5) Date/Time File Pass to 6) Date/Time File Return to