



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: OH VALE			Ref: CS/ASM21008700/Kqce2 Date: 24/11/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	PC 861B	Veh. Inspected	GBB 7276R	
Policy No.	P2420649/00119	Coverage (\$)	0.00	
Claim No.	S1M03FRL	Excess (\$)	0.00	
Assign From	OH VALE	Assign Date	19/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI CANTER (M)	c.c	2977	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	FB70BBA20087	Colour	WHITE	
Odometer	355520 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	AUSTONE	8 mm	
L/H Front Tyre	195 R15X8	AUSTONE	8 mm	
R/H Rear Tyre	195 R15X8 (D)	YOKOHAMA	3/3 mm	
L/H Rear Tyre	195 R15X8 (D)	YOKOHAMA	3/3 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	14/08/2021	Inspection Date	12/11/2021	
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		