



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO21008708/Utf3n2 Date: 27/09/2021 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBJ 7219P	Veh. Inspected	GBJ 4492K
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2102489/SYH	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	19/08/2021
2. Vehicle Particulars & Condition			
Make & Model	NISSAN NV200 DX (A)	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	VM20126870	Colour	BLACK
Odometer	35172 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	165/80 R14	TOYO	6 mm
L/H Front Tyre	165/80 R14	TOYO	6 mm
R/H Rear Tyre	165/80 R14	TOYO	6 mm
L/H Rear Tyre	165/80 R14	TOYO	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND REAR WINDSCREEN SHATTERED.THE CHASSIS FRAME AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/08/2021	Inspection Date	19/08/2021
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	