MG SOLUTION PTE LTD

23 Kaki Bukit Ave 4 (South Wing) #0 4 -0 | Vicom Inspection Centre, Singapore 415933 Tel: 6243 1373 Fax: 6243 1376 Co. Reg. No.: 201427944N

Date : $M = M = M = M = M = M = M = M = M = M $	020142/344N
To: AXA INSULANCE PTE LTD Tel: 1800-880 4741 Fax: Email: Wwter. Survey @ AXG. Com-50	By Fax & Email
Attn: Motor Claims Department	
Dear Sir,	
Re: Accident involving motor vehicle Nos. SKB666Z and PC8370Z along SLIP ROAD FROM TANAN BT. MERAH TOWARDS on 18/07/2011 We are instructed by 7AY POH HOCK (Name of Claimant) to notify you of a road traffic accident on the above mentioned. A copy of the Singapore Accident Statement / Traffic Police Report filed is enclosed. As a result of the accident, our client's / customer's vehicle has been damaged. Before our client / we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a Pre- Repair Survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client / we shall proceed to repair the vehicle without further reference to you.	
Thank you.	FOR SURVEYOR
Yours faithfully,	Please initial here after completion of pre-repair inspection. Thank you. Appointed Surveyor:
MS. NENG OKE HONG HP: 9188 6931	Date & Time of hispection.