

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: SKL 9307Mat Workshop m/s ARCof 38, woodlands Ind Pk E1 H05-18Insured: CTI

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

51K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Repair (m7 - 16K)

Veh No:

SKL 9307MYr Regn: 2014 / 5MType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HYUNDAI DMSANTE PE 24L c.c 2359

Colour:

GREY

A/C: Insured / Std / NI / NA

Sp. Reading

8377

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH5U81BSE U236689Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / Rim / STD A/Rim or

Tyre Size:

F:

235/552R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumiko

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

18/8/21

D.O.I.

24/8/21

Survey held at

ARCDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Company

Vehicle Details

340H

Vehicle No.:

SKL9307M

Vehicle to be Exported:

Yes

Intended Deregistration Date:

19 Aug 2021

Vehicle Make:

HYUNDAI

Vehicle Model:

DM SANTA FE 2.4L GDI ABS D/AB SR 4WD 5DR

Primary Colour:

Silver

Manufacturing Year:

2013

Engine No.:

G4KJDU170539

Chassis No.:

KMHSU81BSEU236689

Maximum Power Output:

141.0 kW (189 bhp)

Open Market Value:

\$24,634.00

Original Registration Date:

08 Jan 2014

First Registration Date:

08 Jan 2014

Transfer Count:

1

Actual ARF Paid:

\$26,488.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

07 Jan 2024

PARF Rebate Amount:

\$15,892.00

Intended COE Rebate Details

COE Expiry Date:

07 Jan 2024

COE Category:

B - Car (1601cc & above)

COE Period(Years):

10

QP Paid:

\$79,300.00

COE Rebate Amount:

\$18,908.00

Total Rebate Amount:

\$34,800.00

The information contained herein is correct as at 19 Aug 2021

OK

Hyundai Santa Fe 2.4A Sunroof

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

新泰興 STHCAR
SING THAI HIN

Price

\$60,300

Depreciation ?

\$15,900 /yr

[View models with similar depre](#)

Reg Date

05-Aug-2014

(2yrs 11mths 11days COE left)

Mileage

53,000 km (7.5k /yr)

Manufactured ?

2014

Road Tax ?

\$1,634 /yr

Transmission

Auto

Dereg Value ?

\$35,489 as of today (change)

OMV ?

\$24,906

COE ?

\$65,700

ARF ?

\$26,869

Engine Cap

2,359 cc

Power

141.0 kW (189 bhp)

Curb Weight ?

1,874 kg

No. of Owners ?

1