

(SAS)

HTM - (SAS)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 17.08.2021

Time: 16:34:06

REPAIR ESTIMATE

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS : CITYCAB PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188

JOB NO : 305483094  
REGN NO : SHA 942G  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 05.01.2017  
DATE/TIME IN : 17.08.2021 10:55  
ACCIDENT DATE : 17.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

|                                                  |    |          |       |        |     |         |
|--------------------------------------------------|----|----------|-------|--------|-----|---------|
| 0001 04-01-0103-2322-A BUMPER COVER FRT          | 1  | 1,052.20 | 20.00 | 841.76 | del |         |
| 0002 04-01-0101-0111-G BUMPER COVER CLIP         | 10 | 22.00    | 20.00 | 17.60  | del | 1074.20 |
| 0003 04-01-0103-0638-G BRKT ASSY-FR BPR UPR SIDE | 1  | 44.80    | 20.00 | 35.84  | Run | 859.36  |

SUB-TOTAL : 895.20

JOB NATURE

|         |                   |        |     |      |
|---------|-------------------|--------|-----|------|
| 0000 PB | PANEL BEATING     | 300.00 | 280 | 780. |
| 0001 SP | SPRAYPAINT CHARGE | 600.00 | 500 |      |

SUB-TOTAL : 900.00

TOTAL : 1,795.20

Jumani  
MVA NAME & SIGNATURE  
DATE: 17/8/21

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE:

Tarphi 97495745  
WP 187871 @ 4pm  
2 days  
C/S Resurf after repair  
fauph C. L. Hanto. a. n

1639.31  
4/5/1300  
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: