

|   |   |          |   |   |   |   |        |   |   |             |
|---|---|----------|---|---|---|---|--------|---|---|-------------|
| ⏪ | < | 1 of 2 ? | > | ⏩ | ↺ | ↻ | 100% ▼ | 🖨 | 📄 | Find   Next |
|---|---|----------|---|---|---|---|--------|---|---|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                                           |      |                                                            |            |
|----------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------|------|------------------------------------------------------------|------------|
| STRIDES AUTOMOTIVE SERVICES PTE LTD<br>60 WOODLANDS INDUSTRIAL PARK<br>E4SINGAPORE 757705                                              |                                                                                                           |      | Ref: CS/SMR21008738/T1uf3<br>Date: 19/08/2021<br>Code: SMR |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                                           |      |                                                            |            |
| Insured Veh.                                                                                                                           | SHB 5819S                                                                                                 |      | Veh. Inspected                                             | SKW 7093J  |
| Policy No.                                                                                                                             |                                                                                                           |      | Coverage (\$)                                              | 0.00       |
| Claim No.                                                                                                                              | TAX/08/21/2039                                                                                            |      | Excess (\$)                                                | 0.00       |
| Assign From                                                                                                                            | HUA YEN                                                                                                   |      | Assign Date                                                | 19/08/2021 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                                           |      |                                                            |            |
| Make & Model                                                                                                                           |                                                                                                           |      | c.c                                                        | 0          |
| Engine No.                                                                                                                             | HIDDEN                                                                                                    |      | Year of Reg.                                               |            |
| Chassis No.                                                                                                                            |                                                                                                           |      | Colour                                                     |            |
| Odometer                                                                                                                               | -                                                                                                         |      | Steering                                                   |            |
| Brakes                                                                                                                                 |                                                                                                           |      | Modification                                               |            |
| General                                                                                                                                |                                                                                                           |      |                                                            |            |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                                           |      |                                                            |            |
|                                                                                                                                        | Size                                                                                                      | Make | Balance                                                    |            |
| R/H Front Tyre                                                                                                                         |                                                                                                           |      | mm                                                         |            |
| L/H Front Tyre                                                                                                                         |                                                                                                           |      | mm                                                         |            |
| R/H Rear Tyre                                                                                                                          |                                                                                                           |      | mm                                                         |            |
| L/H Rear Tyre                                                                                                                          |                                                                                                           |      | mm                                                         |            |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                                           |      |                                                            |            |
|                                                                                                                                        |                                                                                                           |      |                                                            |            |
| <b>5. General Information</b>                                                                                                          |                                                                                                           |      |                                                            |            |
| Accident Date                                                                                                                          | 19/08/2021                                                                                                |      | Inspection Date                                            | 20/08/2021 |
| Survey held at                                                                                                                         | RICO 60 AUTO SERVICES PTE LTD<br>8 KAKI BUKIT AVENUE 4<br>#02-24 PREMIER @ KAKI BUKIT<br>SINGAPORE 415875 |      |                                                            |            |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                                           |      |                                                            |            |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                           |      |                                                            |            |