



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21008760/Uuf3n2	
			Date: 28/09/2021	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SCY 8689T	Veh. Inspected	GBL 2651X	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2102497/GPL	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	20/08/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN NV200 (A)	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	JN1YAAM20Z0001386	Colour	WHITE	
Odometer	5481 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	165/80 R14	TOYO	9 mm	
L/H Front Tyre	165/80 R14	TOYO	9 mm	
R/H Rear Tyre	165/80 R14	TOYO	9 mm	
L/H Rear Tyre	165/80 R14	TOYO	9 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	14/08/2021	Inspection Date	23/08/2021	
Survey held at	LIU'S BROTHER AUTO ENGINEERING WORKSHOP 1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			1 Working Days	