

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 QD:  TP /  S / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s: COMFORT  
 of \_\_\_\_\_  
 Insured: SHC 6283A  
 Policy No: \_\_\_\_\_  
 Claims No: MT/1141509-002  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SHD 3220X Yr Regn: 30 Jun/2016  
 Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: HYUNDAI I40 1.7 c.c. 1685  
 Colour: BLUE A/C: Insured / Std / NI / NA  
 Sp. Reading: 780847 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: KMHLB41UMGU091598\*  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake:  Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi:  Nil / R/Rim / STD A/Rim or \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 2 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

N/S	O/S

Tyre Size: F: 205/60R16  
 R: 205/60R16  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or WESTLAKE  

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm
D.O.A. 19/8/21	D.O.I. 19-08-2021
Survey held at	W/S 4:45PM

 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 O/S FRONT  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
31/8/21	Guo Qiang confirmed Final fig \$780 (Red 1895.60, 70%)

Date/Time, File Pass to?  : Preli. Report  
 : Final Report

Days Of Repair: 2  
 Resurvey No. of Trip: 1

1) \_\_\_\_\_  
 Date/Time, File Return to?  
 2) 31/8/21-Typist  
 Report Subject: TP  
 Lump Sum / IBL: \$780

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Insp (\$ \_\_\_\_\_)  
 : W/weekend (\$ \_\_\_\_\_)

Survey Fee:	
Transportation:	
3 + RS. SI	
Photos	
Other:	
TOTAL	