

H/TME - (C/SUMI)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 19.08.2021

REPAIR ESTIMATE

Time: 13:39:36

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305483583  
REGN NO : SHD3220X  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 30.06.2016  
DATE/TIME IN : 19.08.2021 11:15  
ACCIDENT DATE : 19.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-2322-A	BUMPER COVER FRT	X repair	1	1,052.20	20.00	841.76
0002	04-01-0101-0111-G	BUMPER COVER CLIP	X NA	10 L	22.00	20.00	17.60
0003	04-01-0103-0573-A	PANEL-FENDER RH+	X repair	1	663.00	20.00	530.40
0004	04-01-0103-0638-G	BRKT ASSY-FR BPR UPR SIDE	X NA	1	44.80	20.00	35.84

SUB-TOTAL : 1,425.60

JOB NATURE

0000	PB	PANEL BEATING		600.00	280		
0001	SP	SPRAYPAINT CHARGE		600.00	500		
0002	20-00	TUFF COAT ON AFFECTED PARTS.		50.00	X NA		

SUB-TOTAL : 1,250.00

TOTAL : 2,675.60

Jumani

MVA NAME & SIGNATURE

DATE: 19/8/21

2 Days

4/5

After repair photos.

Geo Qiang

19/8/21 @ 4:45 pm

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: