

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERAL	INSURANCE (S) PL	R	Ref:	CS/AGI21008786/Uuf3n2	
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	D	Date:	29/09/2021	
			C	Code:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SGP 4050L	Veh. Inspected		SMD 4315R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10011349/CD	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		23/08/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	KIA CARENS (A)	c.c		1685	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	KNAHU815VJ7211729	Colour		SILVER	
	Odometer	254495 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/55 R16	MOZZO		6 mm	
	L/H Front Tyre	205/55 R16	MOZZO		6 mm	
	R/H Rear Tyre	205/55 R16	MOZZO		6 mm	
	L/H Rear Tyre	205/55 R16	MOZZO		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	19/08/2021	Inspection Date		24/08/2021	
	Survey held at	TAN LIM MOTOR PTE LTD				
		NO.1 DEFU LANE 6 SINGAPORE 539365				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: