

8010078

GST REG. NO. M2-8921817-3

TOKIO MARINE INSURANCE (S)LTD

20 MCCALLUM STREET #09-01 SINGAPORE SG 069049

Description: 3P 25.08.2020

CONTACT NO: 62216111

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156
7 Sungel Kadut Way Singapore 728791
501 Yishun Industrial Park A Singapore 768732

Page: 1

TAX INVOICE

VEHCLE NO SHC7623X INV. NO/DATE 91526927 05.10.2020

COMPANY REG. NO.: 199506048W

JOB NO. 305418756 MAKE HYUNDAI

MODEL IONIQ(G3) ODOMETER READING

DATE OF REG 14.11.2019 DATE/TIME IN 25.08.2020 12:15

CHASSIS CODE KMHC851CVLU178616

S/No	Part No.		Qty	Unit Price	%Disc	Net
PART	REQUISITION			J-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1		
0001	FNPS	NO PLATE(S)	1	50.00	0.00	50.00
0002	FNPS	NO PLATE(S)	1	50.00	0.00	50.00
0003	04-01-0104-2696	IONIQV4 GRILLE ASSY-RADIATOR#	1	1,409.00	20.00	1,127.20
0004	04-01-0104-2687	IONIOV4 MOULDING-FRONT BUMPER CTR UPR	1	188.00	20.00	150.40
0005	04-01-0104-0578	IONIQV4 COVER-FR BUMPER#	1	418.30	20.00	334.64
0006	04-01-0104-2702	IONIOV4 ABSORBER-FRONT BUMPER ENERGY	1	86.90	20.00	69.52
0007	04-01-0104-2686	IONIOV4 MOULDING-FRONT BUMPER RH	1	93.45	20.00	74.76
8000	04-01-0104-2701	IONIOV4 MOULDING-FRT BPR	1	188.00	20.00	150.40

omfortDelGro Engineering Pte Ltd member of COMFORTDELGRQ

ead Office: 05 Braddell Road ingapore 579701

indly note that no receipt shall be issued unless requested.

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010078	91526927	13,293.08	



GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

vous riups
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156
7 Sungel Kadul Way Singapore 728791
501 Yishun Industrial Park A Singapore 768732

COMPANY REG. NO.: 199506048W Page: 2

8010078

TOKIO MARINE INSURANCE (S)LTD

20 MCCALLUM STREET #09-01 SINGAPORE SG 069049

CONTACT NO: 62216111

VEHCLE NO SHC7623X

INV. NO/DATE 91526927 05.10.2020

MAKE HYUNDAI **JOB NO.** 305418756

MODEL IONIQ(G3)

ODOMETER READING

DATE OF REG 14.11.2019

DATE/TIME IN 25.08.2020 12:15

CHASSIS CODE KMHC851CVLU178616

S/No	Part No.		Qty	Unit Price	%Disc	Net
0009	04-01-0104-3818	IONIOVC BRACKET-FR BUMPER SIDE LH	1	28.00	20.00	22.40
0010	04-01-0104-3918	IONIQVC BRACKET-FR BUMPER SIDE RH	1	28.00	20.00	22.40
0011	04-01-0104-2935	IONIQV4 LAMP ASSY-HEAD RH#	1	1,993.65	20.00	1,594.92
0012	04-01-0104-2835	IONIQV4 LAMP ASSY-HEAD LH#	1	1,993.65	20.00	1,594.92
0013	04-01-0104-0573	IONIQVC PANEL-FENDER RH#	1	490.70	20.00	392.56
0014	04-01-0104-0685	IONIQV1&4 GARNISH ASSY-DELTA RH	1	42.80	20.00	34.24
0015	04-01-0104-3913	IONIOVC EMBLEM-BLUE DRIVE RH	1	26.60	20.00	21.28
0016	04-01-0104-2533	IONIQV2-4 MOULDING ASSY-RR BUMPER CTR	1	451.25	20.00	361.00
0017	04-01-0104-4894	IONIOV4 LAMP ASSY-DAY RUNNING LIGHT LH	1	642.50	20.00	514.00

omfortDelGro Engineering Pte Ltd member of COMFORTDELGRO

ead Office: 5 Braddell Road ngapore 579701

USTOMER'S COPY

ndly note that no receipt shall be issued unless requested.

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010078	91526927	13,293.08	
			7



GST REG. NO. M2-8921817-3

TOKIO MARINE INSURANCE (S)LTD

20 MCCALLUM STREET #09-01 SINGAPORE SG 069049

CONTACT NO: 62216111

8010078

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops
59 Loyang Drive Singapore 508969
383 Sin Ming Dijve Singapore 575717
45 Pandan Road Singapore 609286
320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156
7 Sungei Kadul Way Singapore 728791
501 Yishun Industrial Park A Singapore 768732

COMPANY REG. NO.: 199506048W Page: 3

VEHCLE NO SHC7623X

INV. NO/DATE 91526927 05.10.2020

MAKE HYUNDAI **JOB NO.** 305418756

MODEL IONIQ(G3)

ODOMETER READING

DATE OF REG 14.11.2019

DATE/TIME IN 25.08.2020 12:15

CHASSIS CODE KMHC851CVLU178616

S/No	Part No.		Qty . U	Init Price	%Disc	Net
0018	04-01-0104-4994	IONIOV4 LAMP ASSY-DAY RUNNING LIGHT RH	1	642.50	20.00	514.00
0019	04-01-0104-2551	IONIOVC COVER-RADIATOR GRILLE UPR	1	48.30	20.00	38.64
0020	04-01-0104-0641	IONIQVC CARRIER ASSY-FRONT END MODULE#	1	949.30	20.00	759.44
0021	16-01-0104-0103	IONIQUE RADIATOR ASSY	1	510.50	20.00	408.40
0022	16-01-0104-2076	IONIQVC RADIATOR ASSY-INVERTER	1	884.80	20.00	707.84
0023	16-01-0104-2016	IONIQV2-4 BLOWER ASSY-RADIATOR	1	576.00	20.00	460.80
0024	01-01-0104-2063	IONIQV2&4 TUBE-LIQUID	1	148.50	20.00	118.80
0025	04-01-0104-3949	IONIOV4 FLAP ASSY-ACTIVE AIR UPR RH	1	356.00	20.00	284.80
0026	04-01-0104-3849	IONIQV4 FLAP ASSY-ACTIVE AIR UPR LH	1	356.00	20.00	284.80

omfortDelGro Engineering Pte Ltd member of COMFORTDELGRO

ead Office:

05 Braddell Road ingapore 579701

indly note that no receipt shall be issued unless requested.

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010078	91526927	13,293.08	Y



GST REG. NO. M2-8921817-3

TOKIO MARINE INSURANCE (S)LTD

20 MCCALLUM STREET #09-01 SINGAPORE SG 069049

CONTACT NO: 62216111

8010078

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 608286
320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 728791
501 Yishun Industrial Park A Singapore 768732

COMPANY REG. NO.: 199506048W Page: 4

VEHCLE NO SHC7623X

INV. NO/DATE 91526927 05.10.2020

MAKE HYUNDAI

JOB NO. 305418756

MODEL IONIQ(G3)

ODOMETER READING

DATE OF REG 14.11.2019

DATE/TIME IN 25.08.2020 12:15

CHASSIS CODE KMHC851CVLU178616

S/No	Part No.	20	Qty	Unit Price	%Disc	Net
0027	09-01-0104-2133	IONIQVC ANTENNA ASSY-SMARTKEY	1	40.50	20.00	32.40
0028	04-01-0104-2545	IONIOVC MOULDING-REAR BUMPER LWR CTR	1	47.50	20.00	38.00
0029	01-01-0104-0039	IONIQUE CONDENSER ASSY-COOLER	1	663.60	20.00	530.88
			SUB-TOTAL	:		10,743.44
JOB N	ATURE					
0001	PB	PANEL BEATING		960.00		960.00
0002	SP	SPRAYPAINT CHARGE		600.00		600.00
0003	17-01	CHECK ALL LIGHTING		20.00		20.00
0004	18-01	TO VAC. & TOP UP A/C GAS		100.00		100.00
			SUB-TOTAL	:		1,680.00

omfortDelGro Engineering Pte Ltd member of COMFORIDELGRO

ead Office:

05 Braddell Road ingapore 579701

indly note that no receipt shall be issued unless requested:

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010078	91526927	13,293.08	



GST REG. NO. M2-8921817-3

TAX INVOICE

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 320 Ubi Road 3 Singapore 408649

24 Senoko Loop Singapore 758156 7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 768732

COMPANY REG. NO.: 199506048W Page: 5

8010078

TOKIO MARINE INSURANCE (S)LTD

20 MCCALLUM STREET #09-01 SINGAPORE SG 069049

CONTACT NO: 62216111

VEHCLE NO SHC7623X

INV. NO/DATE 91526927 05.10.2020

MAKE HYUNDAI **JOB NO.** 305418756

MODEL IONIQ(G3)

ODOMETER READING

DATE OF REG 14.11.2019

DATE/TIME IN 25.08.2020 12:15

CHASSIS CODE KMHC851CVLU178616

Items total

12,423.44

Add GST @

7.000 %

869.64

Invoice amount

13,293.08

KATHERINETAN 05.10.2020 15:07:00 CFSO/57/57

Issued by : KATHERINETAN 05
Repair type : CFSO/57/57
Payment Type/Term: /Credit 30 days

omfortDelGro Engineering Pte Ltd member of COMFORTDELGRO

ead Office:)5 Braddell Road

ngapore 579701

ndly note that no receipt shall be issued unless requested.

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010078	91526927	13,293.08	
		L	

Our Ref :	T 0820/ SHC7623X /JW(st
Your Ref :	M2004153/CY

Date :

9-Oct-2020

COMFORTDELGRO ENGINEERING

CDGE Taxi Claims Dept

Singapore 508969

59 Loyang Drive 4th Flr

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

> Mainline +65 6383 6280 Facsimilie +65 6280 9755

> > www.cdge.com.sg

Company Registration No: 199506048W

....

Workshops

Braddell 205 Braddell Road

Singapore 579701

Loyang 59 Loyang Drive Singapore 508969

Sin Ming 383 Sin Ming Drive Singapore 575717

Pandan 45 Pandan Road Singapore 609286

> **Ubi** 320 Ubi Road 3

Singapore 408649

SLK6922A

Sungei Kadut 7 Sungei Kadut Way Singapore 728791

Tokio Marine Insurance Singapore Ltd

20 MaCallum Street #09-01

Tokio Marine Centre

Singapore 069046

WITHOUT PREJUDICE

Attn: Motor Claims Department (Ms Clara Milah Teo)

Dear Sir

ACCIDENT INVOLVING OUR TAXI <u>SHC7623X</u> YOUR INSURED SLK6922A AND OTHER SMP7288C ON 25 Aug 2020

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No: SHC7623X which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to asist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving : we are submitting this claim for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

	011 0 1/11 E11 D 0 E11E1 =		
1	Cost of Repair		\$ 13,293.08
2	4 days Loss of Rental @ \$125.19 per day		\$ 500.76
3	Survey Report Fees (Surveyed by M/s VAC)		\$ 399.11
	GIA / LTA Search Fees		\$ 7.49
5	GIA / Police Report Fees	-	\$ 12
6	Towing / Medical / Transporation Fees		\$ 19
		Sub Total:	\$ 14.200.44

HIRER'S CLAIM

7 <u>4</u> days Loss of Income @ <u>\$ 80.00</u> per day <u>\$ 320.00</u>

Total Claims: \$ 14,520.44

We enclose herewith the following documents to support the claims: -

a) Original repair bill, survey bill/report & original/ scan photographs : ______48 ____pcs.
 b) LTA search slip/s of : SLK6922A

c) GIA / Police report/s of : SHC7623X

d) Letter of authority from owner / hirer / operator

(X) PIR

() Certificate of Insurance (X) Rental Rate Letter

() Photograph/s of Accident Scene (x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully Jim Wong

CDGE Claims Department

Tel: 6214 8374 Fax: 6214 1843 Email: jimwong@cdge.com.sg

This is a computer generated letter. No signature is required.

Atto: Fleat Safety



TAXI BUSINESS

18 SEP 2020

Traffic Police 10 Ubi Avenue 3 Singapore 408865 Tel +65 6547 0000 Fax +65 6547 4883 www.police.gov.sg

Report No Date

: TP/IP/37247/2020 : 9 SEPTEMBER 2020 FLEET SAFETY

TAXI BUSINIO

GOH JOON MENG BLK 533 SERANGOON NORTH AVENUE 4 #12-235 SINGAPORE 550533

1.8 SEP 14.3

FLEET SAFET

CC 20083-75

Dear Sir / Madam,

TRAFFIC ACCIDENT INVOLVING SHC 7623 X, SLK 6922 A AND SMP 7288 C ALONG CENTRAL EXPRESSWAY ON 25/08/2020 AT ABOUT 10.45AM

I refer to the above accident.

- Please be informed that we have completed our investigations which revealed that the driver of <u>SLK 6922 A</u> had committed the offence of Careless Driving under Section 65(1)(a) of the Road Traffic Act Chapter 276 p/u Section 65(5)(a) of the same Act. Action has been initiated against the driver for the said offence.
- 3. If you have any clarification, you may contact the Investigation Officer, Senior Staff Sgt Syed Zayid Muhammad at office number 6547 6404.
- 4. Thank you.

Yours faithfully,

HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE

This is a computer-generated letter. No signature is required.



VICOM LTD

385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555 Facsimile (65) 6458 1040

WWW.Vicom.com.sg Company Registration No: 198100320K

TAX INVOICE

VEHICLE No.

(AIM No.

ACCIDENT DATE :

COMFORTDELGRO ENGINEERING PTE LTD #205 Braddell Road Blk C Ext 1 3rd Level Singapore 579701

ATTN: MOTOR CLAIMS DEPT.

GST REG No. : M9-0000652-A

CUSTOMER ID : VACC0013

INVOICE No. : LY013115

INVOICE DATE: 05/10/2020

305418756

SHC7623X

25/08/2020


INSURED VEH.No: SLK6922A

PAYMENT TERM: 30 Days Credit

DESCRIPTION	QTY	Y UNIT PRICE(SG\$)		AMO	AMOUNT (SG\$)	
Photographs	48		1,.00	\$	48.00	
Transportation	1		50.00	\$	50.00	
VAC Assessment Fee	1	2	75.00	\$	275.00	

373.00 GROSS AMOUNT \$ REMARKS 26.11 CCPL GST @ 7% 399.11 INVOICE AMOUNT \$

This is a computer generated TAX INVOICE No signature required





VICOM LTD

385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555 Facsimile (65) 6458 1040

WWW.VICOm.com.sg Company Registration No: 198100320K

SURVEY REPORT

GENERAL INFORMATION

VAC Ref. No. : 562267 Claim No. : 305418756

Accident Date : 25/08/2020 Claim Type : THIRD PARTY

Assignment Date : 25/09/2020 Policy No. : Survey Date : 25/09/2020 Finalised Dt.:

Survey Report Date: 05/10/2020

VEHICLE PARTICULARS

Vehicle No. : SHC7623X Chassis No. : KMHC851CVLU178616

Registration Date : 14/11/2019 Engine No. : OBSCURED Make : HYUNDAI Engine Cap. : 1580 CC Model : IQNIQ (G3) Transmission : AUTO

Colour : YELLOW

CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)

Foot Brake : SERVICEABLE Steering : SERVICEABLE

Hand Brake : SERVICEABLE Modification : NONE

Mileage :

TYRES	SIZE	MAKE	BALANCE (mm)
FRONT RH		₹.	-
FRONT LH	=	<u>=</u> :	-
REAR RH	≔ □	≅ 7	-
REAR LH	ř. –	₩.	-

SURVEY CONDUCTED AT

59 Loyang Drive Singapore 508969

REMARKS

[1] Workshop Estimate : S\$ 12,623.44 [2] Our Adjustment : S\$ 12,423.44

[3] Repair Period : 5 days

[4] We have not authorised repairs. This survey was carried out on without

prejudice basis.

VICOM LTD SURVEY REPORT

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition	1		Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	1	Radiator Grille	Snapped			1409.00	1409.00
2	1	Front Bumper Moulding	Snapped			188.00	188.00
3	1	Front Bumper	Deformed			418.30	418.30
4	1	Front Bumper Absorber	Snapped			86.90	86.90
5	1	Front Bumper Moulding	Snapped			93.45	93.45
6	1	Front Bumper Moulding Upper	Snapped			188.00	188.00
7	2	Front Bumper Bracket Rh/Lh	Distorted			56.00	56.00
8	2	Headlamp Rh/Lh	Snapped	no support	photo	3987.30	Xnn 3987.30
9	1	Front Fender Rh	Dented		•	490.70	490.70
10	1	Front Fender Garnish Rh	Missing			42.80	42.80
11	1	Front Fender Emblem-Blue Drive Rh	Necessary			26.60	26.60
1	2	Front Day Lamp Rh/Lh	Snapped			1285.00	1285.00
13	1	Radiator Grille Cover	Deformed			48.30	48.30
14	1	Headlamp Support Panel	Snapped			949.30	949.30
15	1	Radiator	Dented			510.50	510.50
16	1	Radiator Invertor	Dented			884.80	884.80
17	1	Radiator Blower	Snapped			576.00	576.00
18	1	A/C Condenser	Dented			663.60	663.60
19	1	A/C Liquid Tube	Dented			148.50	148.50
20	2	Active Flap	Deformed			712.00	712.00
21	1	Rear Bumper Moulding	Deformed			451.25	451.25
22	1	Rear Bumper Lower Moulding	Deformed			47.50	47.50
23	1	Smart Antenna	Snapped			40.50	40.50
			Subtotal	9317		13304.30	13304.30
		Less 20 %		7453.60		2660.86	2660.86
			TOTAL		:	10643.44	10643.44
		SPECIAL NETT ITEM					
1	1	Front Number Plate	Cracked			50.00	50.00
2	1	Rear Number Plate	Cracked			50.00	50.00
			TOTAL	100	: [100.00	100.00
		TOTAL FOR SPARE PARTS			:	10743.44	10743.44

VICOM LTD SURVEY REPORT

Annex B: Adjustment on Labour and Spray Painting

#	Job Description			Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	Labour charges			1000.00	960.00
2	Spray painting charges			700.00	600.00
3	Wiring charges			30.00	20.00
4	Tuff kote (waived)			30.00	0.00
5	Remove/ refix a/c condenser & refil	l gas		120.00	100.00
		TOTAL FOR LABOUR AND SPRAY PAINTING	:	1880.00	1680.00
				-	1680
)	1100 100 0 10 7				

Jummary

Description		Workshop Estimate (S\$)	VAC Adjstment (S\$)
TOTAL FOR SPARE PARTS		10743.44	10743.44
TOTAL FOR LABOUR AND SPRAY PAINTING		1880.00	1680.00
TOTAL REPAIR COST	:	12623.44	12423.44

9233.60 5 days

VICOM LTD SURVEY Report

Our comments and conclusion

We re-appraise the damage shown by the submitted photographs making close references to ComfortDelGro Engineering and would offer our re-appraisal as follows:

For your understanding of our re-appraisal on the parts, the full details are reflected in Annex A of this re-appraisel report.

For labour and spray painting cost, we have re-appraise downwards from \$1,880.00 to \$1,680.00. The reduction is \$200.00

) For your understanding of our re-appraisal on labour/spray painting cost, the full detail are reflected in Annex B of this re-appraisal report.

In total, the repair cost has been reassessed at \$12,423.44 on part by part basis. After having considered extent of damage sustained, point of impact and scope of repairs required. We would state, in conclusion, the claim for the repairs to be considered at \$12,423.44 on a part by part basis as fair and reasonable, within a repair period of five (05) working days.

As between our adjustment of \$12,423.44 and the repair cost of \$12,623.44 by ComfortDelGro, a reduction of \$200.00 resulted.

We submit our re-appraisal report for your kind consideration and would add it was carried out to the best of our ability, knowledge and experience.

Kamarud n Abdul Kadir

for VICOM Ltd







VICOM ASSESSMENT CENTRE VEHICLE No.: SHC7623X ACCIDENT DATE: 25/08/2020







VICOM ASSESSMENT CENTRE VEHICLE No.: SHC7623X ACCIDENT DATE: 25/08/2020







VICOM ASSESSMENT CENTRE VEHICLE No.: SHC7623X ACCIDENT DATE: 25/08/2020







VICOM ASSESSMENT CENTRE VEHICLE No.: SHC7623X ACCIDENT DATE: 25/08/2020







VICOM ASSESSMENT CENTRE VEHICLE No.: SHC7623X ACCIDENT DATE: 25/08/2020







VICOM ASSESSMENT CENTRE VEHICLE No.: SHC7623X ACCIDENT DATE: 25/08/2020







VICOM ASSESSMENT CENTRE VEHICLE No.: SHC7623X ACCIDENT DATE: 25/08/2020







VICOM ASSESSMENT CENTRE VEHICLE No.: SHC7623X ACCIDENT DATE: 25/08/2020







VICOM ASSESSMENT CENTRE VEHICLE No.: SHC7623X ACCIDENT DATE: 25/08/2020



VICOM ASSESSMENT CENTRE VEHICLE No.: SHC7623X ACCIDENT DATE: 25/08/2020







VICOM ASSESSMENT CENTRE VEHICLE No.: SHC7623X ACCIDENT DATE : 25/08/2020








VICOM ASSESSMENT CENTRE VEHICLE No.: SHC7623X ACCIDENT DATE: 25/08/2020




VICOM ASSESSMENT CENTRE VEHICLE No.: SHC7623X ACCIDENT DATE: 25/08/2020







VICOM ASSESSMENT CENTRE VEHICLE No.: SHC7623X ACCIDENT DATE: 25/08/2020







VICOM ASSESSMENT CENTRE VEHICLE No.: SHC7623X ACCIDENT DATE: 25/08/2020







VICOM ASSESSMENT CENTRE VEHICLE No.: SHC7623X ACCIDENT DATE: 25/08/2020

Our Ref: CC20080375

Date: 09 October 2020



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

25/08/2020 @ 10:45 hrs

ALONG

CTE TWDS CITY BEFORE BRADDELL ROAD EXIT

INVOLVING

SLK6922A, SMP7288C

We refer to the above-mentioned accident and wish to inform that CityCab Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHC7623X (the "Taxi"). The Taxi was hired to TAN WAN CHUAN IC NO SXXXX331B a registered hirer-operator of CityCab Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$125.19 per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Philip Chia Manager, Fleet Safety

This is a computer generated letter. No signature is required.

	•		
DATE NAME OF DRIVER MILEAGE READING	AGE HOURS OPERATED (TIME		
108 200 8 1. S COC 80"		DATE. NAME OF DRIVER	ER MILEAC
went Row	1028 JAK 1		
6 4 W C L L C R W . T . L G	8		
T 1 2 8 / 14 1 2 8 / 1			
7 (00.7 0 5	120		
129.5			
100	12 0 4 3 0		
_ -	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
	4 08 30		
	52, 92, 40		
	おかける たはちびは	日本の日間可能に表現の一年の日本の日本	TO SECURE

L	ET	TER	OF	ΔU	THOR	TSAT	MOT

(NAF / PAF)

ACCIDENT INVOLVING Hyundai Ioniq SHC7623X , SLK6922A , S... ON 25-Aug-20 10:45

ALONG

CTE TWDS CITY BEFORE BRADDELL ROAD EXIT

I / We

TAN WAN CHUAN

(Hirer) NRIC No.:

SXXXX331B

and/or

GOH JOON MENG

(Relief) NRIC No.: SXXXX187E

Taxi Number

SHC7623X

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

25-Aug-2020

Name of Hirer

TAN WAN CHUAN

Hirer NRIC

SXXXX331B

Signature:

Address

514 SERANGOON NORTH AVENUE 4...

550514

Contact No.

81261667

Name of Relief

GOH JOON MENG

Relief NRIC

SXXXX187E

Signature:



Address

533 SERANGOON NORTH AVENUE 4 12-235

550533

Contact No.

Enquire Transaction History

Transaction History Details

Log Date/Time:

25 Aug 2020 / 14:19:41

Asset Type:

Vehicle

Transaction Amount:

\$7.49

Asset ID:

SLK6922A

Transaction Type:

18.32 Insurance Enquiry (GIRO Payment) Channel:

External Agency

User ID:

ECENGCCO - GOH CHENG CHUAN

ANDREW CORNELIUS

Business Transaction Reference No.:

20200825141940942102

Search Date / Time:

25 Aug 2020 10:45:00

Insurance Company:

TOKIO MARINE INSURANCE SINGAPORE LTD

Information displayed is correct as at the log date and time.

Enquire Related Logs

Back to List

SHC7623X

LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING Hyundai Ioniq SHC7623X , SLK6922A , S... ON 25-Aug-20 10:45

ALONG

CTE TWDS CITY BEFORE BRADDELL ROAD EXIT

I / We

TAN WAN CHUAN

(Hirer) NRIC No.:

SXXXX331B

and/or

GOH JOON MENG

(Relief) NRIC No.: SXXXX187E

Taxi Number

SHC7623X

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

25-Aug-2020

Name of Hirer

TAN WAN CHUAN

Hirer NRIC

SXXXX331B

Signature:

Address

514 SERANGOON NORTH AVENUE 4...

550514

Contact No.

81261667

Name of Relief

GOH JOON MENG

Relief NRIC

SXXXX187E

Signature :



Address

533 SERANGOON NORTH AVENUE 4 12-235

550533

Contact No.