

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969

Our Ref : 305483858  
Date : 23-8-21  
Time of Fax : \_\_\_\_\_

Via Fax : EMAIL  
Your Insured : XD 9070 H  
Date of Acc : 21-08-21

Attn: Motor Claims Department

Lompae

Dear Sirs

**SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH**

B6L88Y

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
◆ <u>Jumani Bin Masudin</u>	<u>Tel: 6214 8315 or HP: 9635 5305</u>
◆ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
◆ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006

} **jumanibm@cdge.com.sg**  
**Fax no. 6546 8156**

→ If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully



For Vice President  
Taxi Accident Repair

Team: ARC Repair TP(CLS0)1

**JOB CARD**

Sales Order: 4110600

JC NO.: 305483858

TOMER

1S

TOMER NO.

RESS

(R)

(P)

OUNT CARD NO.

**COMFORT TRANSPORTATION PTE LTD**  
**7010045**  
**383 SIN MING DRIVE**  
**Singapore SINGAPORE 575717**  
**65508755**

(O)

REGN NO.:

**SHB6188Y**

MILEAGE

MAKE:

**HYUNDAI**

FUEL

E.....1/2.....F

MODEL

**I-40**

DATE/TIME IN

**21.08.2021 10:40**

YR OF MANU

**24.03.2016**

TARGET DATE

CHASSIS CODE

**KMHLB41UMGU086651**

COMPLETION DATE/TIME:

JOB DESCRIPTION


**Accident Date: 21.08.2021**

**NATURE: 3P 21.08.2021**

S/NO

LABOR CODE

DESCRIPTION



IKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Vo.:

**SHB6188Y**

**JU LONPAC**

Vehicle No.:

**SHB6188Y**

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard


INSURER ENQUIRY

Find  
insurer

Vehicle reg. no.

XD9070H

Date of Accident

21/08/2021 

Reset

% RESULT & RECEIPT

TP Insurer Enquiry

Insurance ..... Lonpac Insurance Bhd

Period of Insurance ..... 02/11/2020 - 01/11/2021

Requested By ..... Por Moy Juan (COMFORTDELG...

Requested Date ..... 23/08/2021 11:04

Payment details

Request Amount: **S\$1.87**

GST Amount: **S\$0.13**

Total Amount Due (GST Inclusive): **S\$2**

General Insurance Association

Records Management Centre

GST Registration No: **M400017735**

Sri B GIPF Y

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305483858  
 REGN NO : SHB6188Y  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : I-40  
 DATE OF REGN : 24.03.2016  
 DATE/TIME IN : 21.08.2021 10:40  
 ACCIDENT DATE : 21.08.2021

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001	04-01-0103-0595-G	PANEL ASSY-RR DR RH#	1	2,201.10	20.00	1,760.88
0002	04-01-0103-0592-G	PANEL ASSY-FR DR RH#	1	2,256.40	20.00	1,805.12
0003	04-01-0103-0723-G	LATCH ASSY-FR DR RH	1	490.80	20.00	392.64
0004	04-01-0103-0845-G	KEY SUB SET-DOOR RH	1	93.25	20.00	74.60
0005	04-01-0103-0860-G	W/STRIP-FR DR BODY SIDE R	1	81.30	20.00	65.04
0006	04-01-0103-0689-G	W/STRIP ASSY-FR DR BELT O	1	75.40	20.00	60.32
0007	04-01-0103-0690-G	MOULDING ASSY-FR DR FRAME	1	153.10	20.00	122.48
0008	04-01-0103-0728-G	HANDLE ASSY-DR O/S	1	132.30	20.00	105.84
0009	04-01-0103-0730-G	COVER-FR DR O/S HDL DRIVE	1	12.60	20.00	10.08
0010	04-01-0103-0727-G	GLASS-FR DR WINDOW RH	1	316.30	20.00	253.04
0011	04-01-0103-0594-G	MIRROR ASSY-RR VIEW O/S R	1	670.00	20.00	536.00
0012	28-01-0103-0003-A	FRT DOOR LOGO SONATA CTPL	1 N	75.00	2.00-	75.00
0013	28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1 N	80.00	0.20	80.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305483858  
REGN NO : SHB6188Y  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 24.03.2016  
DATE/TIME IN : 21.08.2021 10:4  
ACCIDENT DATE : 21.08.2021

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 5,341.04

## JOB NATURE

0000 23-01	TOWING FEE	60.00	
0001 PB	PANEL BEATING	750.00	
0002 SP	SPRAYPAINT CHARGE	750.00	
0003 17-01	CHECK ALL LIGHTING	50.00	
0004 L	TRANSFER DOOR PART	120.00	
0005 20-05	RENEW ADVERTISMENT STICKER-DOOR		200.00
		SUB-TOTAL :	1,930.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305483858  
REGN NO : SHB6188Y  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 24.03.2016  
DATE/TIME IN : 21.08.2021 10:4  
ACCIDENT DATE : 21.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 7,271.04

Jumani

MVA NAME &amp; SIGNATURE

DATE : 23/8/21

AUTHORISED : YES / NO

SURVEYOR NAME &amp; SIGNATURE

DATE :



## JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

### Job Requisition

Date: 21/08/2021 Time Received: 1100		3. Vehicle Type: <input type="checkbox"/> Private <input checked="" type="checkbox"/> Taxi (CTPL/CCPL) <input type="checkbox"/> Fleet <input type="checkbox"/> STK (Boon Lay)		4. Type of Towing: <input checked="" type="checkbox"/> Normal Tow <input type="checkbox"/> King Dolly <input type="checkbox"/> Flat Bed <input type="checkbox"/> Crane-up	
Name of Customer: MQ. Mohd		5. Nature of Service: <input type="checkbox"/> Jumpstart <input type="checkbox"/> Recovery <input type="checkbox"/> Change Tyre / Battery		6. Parts Replaced/Remarks:	
Contact No.: 81892428					
Vehicle No.: SHB6188Y					
Make/Model/Colour: 1-40					
Email:					
Location: 160, Pasir Ris St 13		8. Vehicle Tow - In Workshop:			
Preferred Workshop:		<input type="checkbox"/> Smoky Exhaust <input type="checkbox"/> Wheel Jammed <input type="checkbox"/> Overheating <input type="checkbox"/> Steering Faulty <input type="checkbox"/> Brake Faulty <input type="checkbox"/> Alternator Faulty <input type="checkbox"/> Starting Problem <input type="checkbox"/> Loss Power <input checked="" type="checkbox"/> Accident <input type="checkbox"/> Engine Stalled <input type="checkbox"/> Return Taxi			
<input type="checkbox"/> Braddell <input checked="" type="checkbox"/> Loyang <input type="checkbox"/> Pandan <input type="checkbox"/> Sin Ming <input type="checkbox"/> Sungei Kadut <input type="checkbox"/> Ubi <input type="checkbox"/> Komoco (UBI / Leng Kee) <input type="checkbox"/> Cycle & Carriage (PD) <input type="checkbox"/> Others:					


0. Odometer Reading:

Fuel Level:

F 1/4 1/2 3/4 E

11. Radio / CD Player

☐ OK  
☐ Faulty  
☐ Not tested



# : Cracked X : Dented  
/ : Scatched O : Missing

Signature of Customer

### Job Attended

2. Tow Truck / Recovery Van : ☐ VRS ☐ QA ☒ GAO ☐ OTHERS  
 Name of Driver : HRE  
 Vehicle No. : G128458R  
 Time Dispatch : 1100  
 Time of Arrival : 1130  
 Time Completed : 1215

### Cash Invoice Details (if applicable)

3. Cash Invoice No.:

### Customer Acknowledgement

- I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.  
 I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.  
 Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

21/08/2021

1215

Date

Time

Signature of Customer

### 14. WORKSHOP

Name of Attending Staff/Guard

Date & Time of Arrival

Signature of Attending Staff/Guard

WORKSHOP COPY