

ASS. REC. BY:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

Type: M.Cár / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: _____

Colour: _____

Sp. Reading: _____

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. _____

L/Bal. _____

D.O.A. _____

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Returned:

☐ : Preli. Report☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Insp (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Other: _____

Lorpal (L8um)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 23.08.2021

Time: 12:02:42

Page: 1

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305483858
REGN NO : SHB6188Y
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 24.03.2016
DATE/TIME IN : 21.08.2021 10:40
ACCIDENT DATE : 21.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0595-G	PANEL ASSY-RR DR RH#	1	2,201.10	20.00	1,760.88
0002 04-01-0103-0592-G	PANEL ASSY-FR DR RH#	1	2,256.40	20.00	1,805.12
0003 04-01-0103-0723-G	LATCH ASSY-FR DR RH	1	490.80	20.00	392.64
0004 04-01-0103-0845-G	KEY SUB SET-DOOR RH	1	93.25	20.00	74.60
0005 04-01-0103-0860-G	W/STRIP-FR DR BODY SIDE R	1	81.30	20.00	65.04
0006 04-01-0103-0689-G	W/STRIP ASSY-FR DR BELT O	1	75.40	20.00	60.32
0007 04-01-0103-0690-G	MOULDING ASSY-FR DR FRAME	1	153.10	20.00	122.48
0008 04-01-0103-0728-G	HANDLE ASSY-DR O/S	1	132.30	20.00	105.84
0009 04-01-0103-0730-G	COVER-FR DR O/S HDL DRIVE	1	12.60	20.00	10.08
0010 04-01-0103-0727-G	GLASS-FR DR WINDOW RH	1	316.30	20.00	253.04
0011 04-01-0103-0594-G	MIRROR ASSY-RR VIEW O/S R	1	670.00	20.00	536.00
0012 28-01-0103-0003-A	FRT DOOR LOGO SONATA CTPL	1	75.00	2.00-	75.00
0013 28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1	80.00	0.20	80.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305483858
 REGN NO : SHB6188Y
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 24.03.2016
 DATE/TIME IN : 21.08.2021 10:4
 ACCIDENT DATE : 21.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 5,341.04

JOB NATURE

0000 23-01	TOWING FEE	60.00	?
0001 PB	PANEL BEATING	750.00	560
0002 SP	SPRAYPAINT CHARGE	750.00	500
0003 17-01	CHECK ALL LIGHTING	50.00	X NN
0004 L	TRANSFER DOOR PART	120.00	/
0005 20-05	RENEW ADVERTISMENT STICKER-DOOR	200.00	.

SUB-TOTAL : 1,930.00

4 Days
 Upon repair
 After repair photos
 Eric Qian
 23/8/21 spm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING PTE LTD

Date: 23.08.2021

Time: 12:02:42

REPAIR ESTIMATE

Page: 3

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305483858
REGN NO : SHB6188Y
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 24.03.2016
DATE/TIME IN : 21.08.2021 10:4
ACCIDENT DATE : 21.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 7,271.04

Jumani

MVA NAME & SIGNATURE

DATE : 23/8/21

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :