



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:JANICE KOH			Ref: CC4/ASM21008828/Aps3q2 Date: 03/01/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SDD 2969Z	Veh. Inspected	SLU 8526U	
Policy No.	GA370865	Coverage (\$)	0.00	
Claim No.	S1M03G7A	Excess (\$)	0.00	
Assign From		Assign Date	23/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. 216I	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	WBA2D920705E91622	Colour	GREY	
Odometer	87863 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R17	MICHELIN	6 mm	
L/H Front Tyre	205/55 R17	MICHELIN	6 mm	
R/H Rear Tyre	205/55 R17	MICHELIN	6 mm	
L/H Rear Tyre	205/55 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/08/2021	Inspection Date	24/08/2021	
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	