

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AXA	DATE	: 23/08/2021
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SLU8526U	WBA 2D820705E91622	
MODEL	: BMW 216D		
CHASSIS NO		Xiao Tony	
<u>ACCIDENT DETAILS</u>		DATE	: 20-Aug-21
		TIME	: 15:45HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>phd</i>	1	\$ 1,855.30	\$ 1,855.30 <i>1180</i>
2	REAR BUMPER SIDE RETAINER <i>new RIT</i>	2	\$ 120.00	\$ 240.00 <i>120</i>
3	REAR BUMPER REFLECTOR RH <i>new</i>	1	\$ 210.30	\$ 210.30 <i>X</i>
4	REAR FENDER RH <i>Regis</i>	1	\$ 2,553.20	\$ 2,553.20 <i>X</i>
TOTAL PRICE				\$ 4,858.80
LESS 10%				\$ 485.88
SUB TOTAL PRICE				\$ 4,372.92

1300
1170

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP(SET) <i>new</i>	1	\$ 22.00	\$ 22.00
2	WHEEL RIM RH <i>ht</i>	1	\$ 1,400.00	\$ 1,400.00 <i>700</i>
TOTAL				\$ 1,400.00

722

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,000.00	400	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	400	

3	WIRING CHECK	\$ 30.00	✓	
4	REMOVE AND REFIX REAR REVERSE SENSOR	\$ 1,000.00	50	
5	FOUR WHEEL ALIGNMENT	\$ 120.00	80	
6	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00	X	

960

TOTAL

\$3,400.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,772.92
TOTAL LABOUR COST : \$ 3,400.00
TOTAL REPAIR COST : \$ 9,172.92

Adnan
E/C 24/08/21.
03 Days.

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

total: 2852
4/5: 2250

PART BY PART / LUMP SUM :

NO OF DAYS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: