



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (S) PTE LTD 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807			Ref: CS/MSG21008853/Duf3e2	
			Date: 11/11/2021	
			Code: MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FORKLIFT		Veh. Inspected	SMV 1131D
Policy No.	300442857 CGL		Coverage (\$)	0.00
Claim No.	261515		Excess (\$)	0.00
Assign From	LIM ZI LIANG		Assign Date	24/08/2021
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE		c.c	1496
Engine No.	HIDDEN		Year of Reg.	2020
Chassis No.	GK82102263		Colour	BLACK
Odometer	10046 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	5 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	5 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	5 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/08/2021		Inspection Date	24/08/2021
Survey held at	JWG INTERNATIONAL PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	