

ASS. BY:

REF:

CS/MSG21008853/Duf3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / ☒ FWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMV 1131D

at Work on m/s _____

of _____

Insured ☒ FORKLIFT

Policy # 300442857 CGL

Claim # 261515

Sum Insured: _____ Excess: _____

(Client Record)

Make of Veh: _____

(Police Condition)

Remarks: The veh had commenced its repair at the time of inspection.

Bal. of Market Value: _____

IDAC Accident Report Consistent? : Yes or No

GIA / IR Seen Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lump Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMV 1131D Yr Regn: Sept 2020

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Honda Shuttle C.D. 1496

Colour: Black A/C: Insured / Std / RI / NA

Sp. Reading: 10046 T/Radio: Insured / Std / RI / NA

Eng No: L15B6022667

C/No: GK82102263

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / STD A/Rim or

Tyre Size: F: 185 / 60 R15

R: ———— " ————

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMAI /

TOYO / YOKO or

Yokohama

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 20/08/2021

D.O.L. 24/08/2021

Survey held at JWG AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time Action/Instruction

MSG Forklift

Confirmed L/S \$4000, 4 repair days
(RED \$26951.20; 87%)

Date/Time, File Pass to?

5/11 TYPIST

Date/Time, File Return to?



: Prel. Report



Final Report

TP

L/s \$4000

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: MSIG INSURANCE SINGAPORE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SMV1131D [OUR CLIENT] ON 20/08/2021

ESTIMATED REPAIR COSTS FOR SMV1131D

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	BONNET NW	\$ 2,398.00	X
1PC	BONNET INSULATOR NW	\$ 410.00	X
1PC	BONNET LOCK NW	\$ 382.00	X
2PCS	BONNET HINGE LH / RH @ \$129.00 EACH NW	\$ 258.00	X
1PC	BONNET SEAL NW	\$ 194.00	X
1PC	FRONT GRILLE NW	\$ 892.00	X
1PC	FRONT GRILLE BASE NW	\$ 771.00	X
1PC	FRONT GRILLE CHROME NW	\$ 695.00	X
1PC	FRONT GRILLE LOGO NW	\$ 101.00	X
2PCS	HEAD LAMP LH / RH @ \$2,419.00 EACH NW	\$ 4,838.00	X
2PCS	HEAD LAMP CHROME MOULDING LH / RH @ \$231.00 EACH NW	\$ 462.00	X
2PCS	HEAD LAMP LOWER BRACKET LH / RH @ \$198.00 EACH NW	\$ 396.00	X
2PCS	HEAD LAMP CONTROL MODULE LH / RH @ \$1829.00 EACH NW	\$ 3,658.00	X
1PC	FRONT BUMPER damaged 925.70	\$ 1,140.00	✓
2PCS	FRONT BUMPER SIDE RETAINER LH / RH @ \$85.00 EACH NW	\$ 170.00	X
1PC	FRONT BUMPER GRILLE damaged 186.70 NW	\$ 495.00	✓
2PCS	FRONT BUMPER FOG LAMP LH / RH @ \$410.00 EACH o/s monthly rate	\$ 820.00	✓
2PCS	FRONT BUMPER FOG LAMP GARNISH LH / RH @ \$298.00 EACH HS	\$ 596.00	X 271.20
2PCS	FRONT BUMPER FOG LAMP HOLDER LH / RH @ \$241.00 EACH NW	\$ 482.00	X 194.90
2PCS	FRONT BUMPER FOG LAMP CHROME LH / RH @ \$290.00 EACH NW	\$ 580.00	✓
1PC	FRONT BUMPER TOW HOOK COVER NW	\$ 94.00	X
1PC	FRONT BUMPER SPONGE NW	\$ 324.00	X
1PC	FRONT BUMPER UNDER COVER NW	\$ 439.00	X
1PC	FRONT REINFORCEMENT BAR NW	\$ 990.00	X
1PC	FRONT SUPPORT PANEL Damaged 631.20	\$ 1,982.00	✓
1PC	FRONT SUPPORT PANEL TOP GARNISH NW	\$ 321.00	X
1PC	A/C CONDENSOR NW	\$ 1,782.00	✓
1PC	A/C CONDENSOR DISCHARGE HOSE NW	\$ 879.00	X
1PC	A/C CONDENSOR SUCTION HOSE NW	\$ 375.00	X
1PC	RADIATOR ASSY NW	\$ 2,194.00	✓
1PC	RADIATOR FAN MOTOR NW	\$ 452.00	X

1PC	RADIATOR FAN BLADE NW	\$ 198.00	X
1PC	RADIATOR FAN COWLING NW	\$ 501.00	X
1PC	WIPER WASHER TANK NW	\$ 295.00	X

4580.10

3664.08

PARTS SUM: \$ 30,564.00
 PARTS LESS 20%: \$ 6,112.80
 PARTS TOTAL: \$ 24,451.20

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY BONNET INSULATOR CLIPS NW	\$ 50.00	X
*	TO SUPPLY FRONT GRILLE CLIPS NW	\$ 50.00	X
*	TO SUPPLY HEAD LAMP CLIPS NW	\$ 50.00	X
*	TO SUPPLY FRONT BUMPER CLIPS NW	\$ 50.00	20/-
*	TO SUPPLY FRONT BUMPER GRILLE CLIPS NW	\$ 50.00	20/-
*	TO SUPPLY FRONT BUMPER FOG LAMP GARNISH CLIPS NW	\$ 50.00	X
*	TO SUPPLY FRONT NO. PLATE & CASING NW	\$ 100.00	X
*	TO SUPPLY COOLANT NW	\$ 100.00	X
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 2,400.00	600/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 2,400.00	300/-
*	TO TUFF COAT DAMAGED AREAS	\$ 300.00	NW
*	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	\$ 200.00	120/-
*	TO RNR RADIATOR & REFILL COOLANT TO FACILITATE REPAIRS	\$ 200.00	50/-
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00	80/-
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00	150/-

LABOUR & S/N TOTAL: \$ 6,500.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 30,951.20

24/08/2021 @ 1000hrs

N/A Actual

2/sum 4 days.

N/A

LKK Auto

5004.08

4/5 4,000/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	23/08/2021 09:38 (SGT)
Date of Accident	20/08/2021 17:40 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	14 PENJURU CLOSE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMV1131D
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	LUO ZIJUN
NRIC No	SXXXX458G
Email Address	yanlin1986@msn.com
Mobile Phone No	(Phone) +65-98169418
Alternative Phone No	+65-98169418

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Shuttle
Variant	1.5G CVT SENSING
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1496

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	-
Cover Note Number	-

DRIVER

Name of Driver	YAN LIN
NRIC No	SXXXX398G

Date Of Birth	07/12/1986
Occupation	Indoor
Date Of Driving Pass	21/09/2015
Driving experience	5 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96395785
Alt. Phone Number	-
Email Address	yanlin1986@msn.com
Address	273A JURONG WEST AVENUE 3 #07-41 SPORE 641273
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Spouse
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	-
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	NA / Unknown
Name of Driver	-
Contact Number	-
Address	-
Address complement	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan

14 Penjuru Close

Vehicle A: SMV 1131D

Vehicle B: Forklift



Describe Circumstances of the Accident

On the stated date & time, I, vehicle A (SMV1131D) was travelling straight to exit the carpark. Suddenly, I saw vehicle B (Forklift) coming from the opposite direction, I stop and applied horn, but vehicle B (Forklift) was still moving forward to my direction. I start to reversed but vehicle B (Forklift) still collided on the front portion of my vehicle causing damages.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time:

Driver's Signature (if driver is not the policyholder) / Date & Time:

Witnessed by Reporting Centre Personnel

Back to OneMotoring

enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Singapore NRIC

Vehicle Details

458G

Vehicle No.:

Vehicle to be Exported:

SMV1131D

Intended Deregistration Date:

Yes

Vehicle Make:

23 Aug 2021

Vehicle Model:

HONDA

Primary Colour:

SHUTTLE 1.5G CVT SENSING

Manufacturing Year:

Black

Engine No.:

2019

Chassis No.:

L15B6022667

Maximum Power Output:

GK82102263

Open Market Value:

95.0 kW (127 bhp)

Original Registration Date:

\$21,759.00

First Registration Date:

16 Sep 2020

Transfer Count:

16 Sep 2020

Actual ARF Paid:

0

Intended PARF Rebate Details

\$12,463.00

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

15 Sep 2030

PARF Rebate Amount:

\$9,347.00

Intended COE Rebate Details

COE Expiry Date:

15 Sep 2030

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$37,766.00

COE Rebate Amount:

\$30,212.00

Total Rebate Amount:

\$39,559.00

The information contained herein is correct as at 23 Aug 2021

OK

OK