

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX SINGAPORE 069110 INV No. AC2107660

INV Date 08/11/2021

Reference CS/EQI21008859/Gtf3e2

Code EQI

#### PROFESSIONAL SERVICE FEE

Vehicle No. SKV 2962P

Insured Veh. GBJ 8780C

Claim No. DM21HO01226/MT

Policy No. DMCPHQ20-003564

Accident Date 20/08/2021

Inspection Date 24/08/2021

Description	Total
Survey Inspection	230.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	230.00
GST (7%)	16.10
Grand Total	246.10

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

**KHM** 



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

		Affiliated to Federation Internation	nale Des Experts En A	utomok	pile						
	EQ INSURANCE C	OMPANY LTD	R	tef:	CS/EQI21008859/Gtf3e2						
	5 MAXWELL ROAI #17-00 TOWER BL MND COMPLEXSI		D	ate:	08/11/2021						
			С	ode:	EQI						
1.		Policy Particulars :	- THIRD PARTY O	CLAIM							
	Insured Veh.	GBJ 8780C	Veh. Inspected		SKV 2962P						
	Policy No.	DMCPHQ20-003564	Coverage (\$)		0.00						
	Claim No.	DM21HO01226/MT	Excess (\$)		0.00						
	Assign From	MELODY TEOH	Assign Date		24/08/2021						
2.		Vehicle Partic	ulars & Condition	n							
	Make & Model	NISSAN QASHQAI	c.c		1197						
	Engine No.	HIDDEN	Year of Reg.		2015						
	Chassis No.	SJNFEAJ11U1462981	Colour		RED						
	Odometer	58473 KM	Steering		IN ORDER						
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM						
	General	GOOD									
3.	Conditions of Tyres										
		Size	Make		Balance						
	R/H Front Tyre	215/60 R17	LING LONG		6 mm						
	L/H Front Tyre	215/60 R17	LING LONG		6 mm						
	R/H Rear Tyre	215/60 R17	LING LONG		6 mm						
	L/H Rear Tyre	215/60 R17	LING LONG		6 mm						
4.		Description	on of Damages								
	THE VEHICLE SUS	STAINED DAMAGES AT THE REA	AR PORTION.								
	DAMAGES SEE DI	ETAILS.									
5.		General	Information								
	Accident Date	20/08/2021	Inspection Date		24/08/2021						
	Survey held at	KAI LIANG MOTOR SERVICE									
	BLK 1 KAKI BUKIT AVE 6 #01-101 AUTOBAY @KAKI BUKIT SINGAPORE 417883										
5a.		Re	emarks								
		ON WAS CONDUCTED ON A"WITH CE TO YOUR INSTRUCTIONS, WI									
5b.	Estimate Days of Repair										
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	5	Worki	ng Days						



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 2962P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)	
	REPLACEMENT OF PARTS				
1	REAR BOOT DOOR (N)	BUCKLED	3,368.90	2,936.80	
1	REAR BUMPER (N)	TORN	796.70	717.00	
1	BUMPER SIDE BRACKET (N)	NOT NECESSARY	48.90	-	
1	BUMPER REINFORCEMENT (N)	TO REPAIR SEE LABOUR	691.50	-	
1	REAR WINDSCREEN GLASS AND WINDSCREEN MOULDING (N)	SCRATCHED	1,306.80	930.00	
1	REAR BOOT LOWER END PENAL (INNER AND OUTER) (N)	TO REPAIR SEE LABOUR	482.60	-	
1	REAR DOOR INNER LOCK AND LOCK MOTOR (N)	NOT NECESSARY	190.50	-	
1	REVERSE CAMERA (N)	NOT NECESSARY	350.00	-	
1	NUMBER PLATE LAMP GARNISH (N)	DEFORMED	249.30	249.30	
2	REAR LAMP @\$295.30 (N)	NOT NECESSARY	590.60	-	
1	REAR RUNNER STRIP (N)	NOT NECESSARY	230.00	-	
	LESS 10% DISCOUNT		-	-483.31	
			8,305.80	4,349.79	
	SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	DAMAGED	480.00	200.00	
1	REAR WINDSCREEN GUM (SN)	NECESSARY	120.00	30.00	
			600.00	230.00	
	<u>LABOUR</u>				
	CHANGE REAR LAMP, REVERSE SENSOR, CAMERA WIRING LABOUR.		200.00	40.00	
	CHANGE REAR WINDSCREEN LABOUR.		150.00	120.00	
	KNOCKING & WELDING BODY WORKS. INCLUSIVE OF THE REPAIR OF BUMPER REINFORCEMENT AND REAR BOOT LOWER END PENAL (INNER AND OUTER).		1,000.00	400.00	
	RE-SPRAY PAINT WORK.		950.00	600.00	
	APPLY ANTI RUST ON AFFECT PARTS.	NOT NECESSARY	180.00	-	
			2,480.00	1,160.00	
	GRAND TOTAL		11,385.80	5,739.79	

Report Ref No. CS/EQI21008859/Gtf3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS	4,600.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/EQI21008859/Gtf3e2

XING GUO QIANG

M.MATAI, AMSAE-A

**Automotive Assessor** 

X.S.

**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

# **SINGAPORE ACCIDENT STATEMENT**

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

  5. Any false reporting may be referred to the Police for investigation.

  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving

- and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

Date of Submission 20/08/2021 18:59 (SGT) Date of Accident 20/08/2021 12:30 (SGT) Exact Location of Accident Singapore Additional Location Information Bedok North Road Country/State of Loss Singapore

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SKV2962P

#### INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner Yong Mee Keow NRIC No. S1241218E Email Address info@indusmat.com.sq Mobile Phone No (Phone) +65-98305962 Alternative Phone No +65-98305962

#### VEHICLE PARTICULARS

Manufacturer

Nissan Model Qashqai Variant Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Private car

Transmission Auto CC 1198

#### **INSURANCE COMPANY**

Name of Insurance Company Tokio Marine Insurance Singapore Ltd Type of Coverage Comprehensive Fleet Policy Policy Number 21\*MR000012-R01 Cover Note Number

#### DRIVER

Name of Driver Yong Mee Keow NRIC No. S1241218E

Date Of Birth 06/02/1957 Occupation Indoor Date Of Driving Pass 30/12/1982 Driving experience 38 YEARS AND 8 MONTHS Gender Female Mobile Number (Phone) +65-98305962 Alt. Phone Number +65-98305962 Email Address info@indusmat.com.sg Address Blk102 Bedok North Ave 4 #03-2046 Address complement Postcode 460102 Is the driver the policyholder? Yes If No. Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Raining Road Surface Wet OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No **DETAILS OF POLICE ACTION** Was the accident reported to the police? Nο Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT Refer to attached report ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Reasons for not uploading a video of the accident With workshop Was there any audio recorded? **DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number	GBJ8780C
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-

Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver) -

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful</u> and accurate as <u>possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Tunderstand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the haurers law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as wall as on the external cover of envelopes/mail peckages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Parsonal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agants (including their lawyers/law firms), which may be sited outside of Sisgapore, for one or more of the above Purposes.

Policyholder's Signature Date & Driver's Signature (II driver is not the policyholder) / Date Reporting Cartice Personnel

Sketch Plan

A SKV 3962 P

B 687 8780 C

L	101	was	dri	ving	al	ong	Beo	lok	HOH	th 1	Rom	d	and	2,	toppe
vel	rich	e C	e b	878	o C	10 K	t c	ed	my	ye Co	10w	Pa	<u>~</u> .	C	toppe
									J						
				// /											
				-27/-											
						Call!									
				70											
													7150		
								1,511							

I'We declare the foregoing particulars are true in every respect.

Witnessed by Reporting Centre Personnel



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SKV 2962P


### **INSPECTION**















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SKV 2962P

### **RE-INSPECTION**















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### PHOTOGRAPHS FOR VEHICLE NO. SKV 2962P

### **RE-INSPECTION**











