Surveyor :

REF: CS/LAW21008892/Dqf3

Special Instruction:

L/SUM : $ 13000.00

Third Parties:

Claimant:

Surveyor: Precise Appraisal PL

Workshop: TEAM AUTOPRO PTE LTD

ASSIGNMENT (Office)

From (Person): TEO YI XUAN of SMO Date/Time: 24/8/2021 4:24 PM

Estimated Cost: Bill to:

OD / TP Re-inspection / Evaluation

To Inspect Vehicle No: GBG 9907P Insured: GBJ 8924E

at Workshop m/s TEAM AUTOPRO PTE LTD Tel: 6258 1955

of 160 SIN MING DR #01-14 SIN MING AUTO CITY

Policy No: 2021000383.Sompo Claim No: CMTD2002954/THE

Sum Insured: Excess:

Make of Veh: D.O.A. 08/10/2020

(Client's Record)

10-09-21- 1.30p.m

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig ___, ___days (Red $___/___%; Original 9 days)

Date/Time: 24/12/21 Submit ~~Final Fig~~ LS $6500, 6 days (Red $ 6250 /49 %; Original 9 days)

Date/Time	Action/Instruction
	GBG 9907P-NBA/AIG20010942/Y DOA : 08/10/2020doabdoa :
	GBJ 8924E- NBA/AIG20010942/Y DOA : NBA/AIG20010942/Y

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : *NC*)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/ Evaluated by:

Fee Charged:	*Date:*
Basic & Add	
Transport	
Photos	
Others	
Total	

1) Date/Time 24/12/21 File Pass to Typist 2) Date/Time File Return to

3) Date/Time File Pass to 4) Date/Time File Return to

5) Date/Time File Pass to 6) Date/Time File Return to