



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL C/O : KELVIN CHIA PARTNERSHIP 6 TEMASEK BOULEVARD 29TH FLOOR SUNTEC TOWER FOUR SINGAPORE 038986			Ref: CS/LAW21008892/Dqf3e2	
			Date: 27/01/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	GBJ 8924E	Veh. Inspected	GBG 9907P	
Policy No.	2021000383.Sompo	Coverage (\$)	0.00	
Claim No.	CMTD2002954/THE	Excess (\$)	0.00	
Assign From	TEO YI XUAN	Assign Date	24/08/2021	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV350	c.c	2488	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JN1MC2E26Z0008557	Colour	SILVER	
Odometer	110395 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	BRIDGESTONE	5 mm	
L/H Front Tyre	195 R15	BRIDGESTONE	5 mm	
R/H Rear Tyre	195 R15	BRIDGESTONE	5 mm	
L/H Rear Tyre	195 R15	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	08/10/2020	Inspection Date	10/09/2021	
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	