

INC  
ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No. MT/1141999-002

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SH 8326R Yr Regn: 4 Jan 2017Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai : 4067 c.c. 1685

Colour

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

77022

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNULB41UMHU098188

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: W / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Giti

Front

Rear

R/Bal.

6 mm

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

D.O.I.

23-08-21

Survey held at

W/SupmDes. of Damages: Frt / Rear / O/S / NIS / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LS \$750 (Red \$3250.62, 81%)

Date/Time, File Pass to?

☐

: Preli. Report

1) 09/12 Typist

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Wheel Insp (\$

Survey Fee:

Transportation:

3 + RS. \$

Photos

Other:

TOTAL

Report Form:

TP

Lump Sum / Fee: 750

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305483853  
 REGN NO : SH 8326R  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : I-40  
 DATE OF REGN : 11.01.2017  
 DATE/TIME IN : 23.08.2021 08:20  
 ACCIDENT DATE : 22.08.2021

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

|      |                   |                           |          |   |          |       |          |
|------|-------------------|---------------------------|----------|---|----------|-------|----------|
| 0001 | 04-01-0103-0593-G | PANEL ASSY-FR DR LH#      | X Repair | 1 | 2,256.40 | 20.00 | 1,805.12 |
| 0002 | 04-01-0103-0600-G | MIRROR ASSY-O/S REAR VIEW | X Repair | 1 | 570.00   | 20.00 | 536.00   |
| 0003 | 28-01-0103-0003-A | FRT DOOR LOGO SONATA CTPL | X        | 1 | 75.00    | 10.00 | 67.50    |
| 0004 | 28-01-9999-2023-A | APP LOGO REAR DOOR L/R CT | X        | 1 | 80.00    | 10.00 | 72.00    |

SUB-TOTAL : 2,480.62

## JOB NATURE

155

139.5

|      |       |                    |        |       |
|------|-------|--------------------|--------|-------|
| 0000 | PB    | PANEL BEATING      | 600.00 | 280   |
| 0001 | SP    | SPRAYPAINT CHARGE  | 750.00 | 28500 |
| 0002 | 17-01 | CHECK ALL LIGHTING | 50.00  | X     |
| 0003 | L     | TRANSFER DOOR PART | 120.00 | X     |

SUB-TOTAL : 1,520.00 919.5

-20%: 750

2 Days  
 4/5  
 After repair photos  
 Give QAP  
 Upon 23/8/21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date: 23.08.2021

Time: 10:33:02

Page: 2

## REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

|               |   |                 |
|---------------|---|-----------------|
| JOB NO        | : | 305483853       |
| REGN NO       | : | SH 8326R        |
| MILEAGE       | : | 0000000000      |
| MAKE          | : | HYUNDAI         |
| MODEL         | : | I-40            |
| DATE OF REGN  | : | 11.01.2017      |
| DATE/TIME IN  | : | 23.08.2021 08:2 |
| ACCIDENT DATE | : | 22.08.2021      |

### JOB / PARTS DESCRIPTION

[illegible]

TOTAL : 4,000.62

MVA NAME & SIGNATURE  
DATE: 22/8/21

\_\_\_\_\_ AUTHORIZED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

