# **SINGAPORE ACCIDENT STATEMENT**

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

  5. Any false reporting may be referred to the Police for investigation.

  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving

- and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## **ACCIDENT STATEMENT**

Date of Submission 25/08/2021 09:47 (SGT) Date of Accident 24/08/2021 08:20 (SGT) Exact Location of Accident SLE, Singapore Additional Location Information TOWARDS CTE AFT WOODLANDS AVE 12 EXIT Country/State of Loss Singapore

# **DETAILS OF OWN VEHICLE**

Toyota

Vehicle Registration Number GBE3429C

#### INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner WINTER AIR PTE LTD Company Reg No 2XXXXXX009H Email Address winter.air@gmail.com Mobile Phone No (Phone) +65-90046608 Alternative Phone No +65-90046608

## VEHICLE PARTICULARS

Manufacturer

Model Hiace Variant Exact purpose for which vehicle was being used at time of Employment accident Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Commercial vehicle Transmission Manual CC 2494

## **INSURANCE COMPANY**

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd. Type of Coverage Comprehensive Fleet Policy Policy Number 2070148783 Cover Note Number

# DRIVER

Name of Driver **MOTALEB** Passport No/FIN GXXXX759U

Date Of Birth Occupation Date Of Driving Pass Driving experience Gender Mobile Number Alt. Phone Number Email Address Address Address Address Address complement Postcode Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver	17/08/1985 Outdoor 29/03/2015 6 YEARS AND 5 MONTHS Male (Phone) +65-89056159 - mdmotalebm715@gmail.com 7 MANDAI LINK #07-39 MANDAI CONNECTION 728653 No Employee No
Type of Accident Weather Conditions Road Surface	Chain Collision Raining Wet
Was any foreign vehicle involved in the accident?  Number of vehicles involved in the accident  Was anybody injured in the Accident?  Was any injured conveyed to hospital by ambulance?  Was any other vehicle or property damaged?  Number of Passengers (Including Driver)  Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?  PASSENGER 1	No 3 Yes No Yes 2 No
Name Gender	HASAN MAHEDI Male
DETAILS OF POLICE ACTION	
Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom?	No No -
CIRCUMSTANCES OF ACCIDENT	
PLS REFER TO THE ATTACHED STATEMENT.  ATTACHMENT(S)	
Are accident photos available for attachment? Was there any video captured by Car Camera? Reasons for not uploading a video of the accident Was there any audio recorded?	Yes Yes WITH WORKSHOP No
DETAILS OF OTHER	VEHICLE PROPERTY 1
Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour	SMM1817G - - -

Vehicle Category	Private car
Name of Driver	-
Contact Number	_
Address	_
Address complement	_
Postcode	_
Insurance Company Name	_
Nature Of Damage	_
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	_
<b>5</b> ( <b>5</b> )	

# DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number Vehicle Manufacturer	GBB6856Z -
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	_
	_

# INJURED PERSONS DETAILS

# INJURED 1

Name of injured person Gender Phone No Address Address Complement Post Code Approximate Age Years Old Injuries Sustained Injured person in which vehicle? Were seat belts worn? Was this injured conveyed to hospital by ambulance?	MOTALEB Male SLIGHT GBE3429C Yes No
INJURED 2	
Name of injured person Gender Phone No Address Address Complement Post Code Approximate Age Years Old Injuries Sustained Injured person in which vehicle? Were seat belts worn? Was this injured conveyed to hospital by ambulance?	HASAN MAHEDI Male SLIGHT GBE3429C Yes No

## SKETCH PLAN

#### IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Formmust be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that

- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the 'Personal Information') and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the 'Insurers'), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the 'Purposes')

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers law yers/law firms, may/are permitted to collect, use, disclose and/or process my Parsonal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

The state of the s

Policyholder's Signature / Date & Time

Driver's Signature (# driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

(1) GBE 3429C.

(B)

(c) GBB 6856Z

SLE towards CTE after woodlands Ave 12 exit.

- Nakala - E

aribe Circumstances of the Accident  On Super 201 at Q 0820 drs, I was Insulating in my vehicle 388 3409 C) along SLE towards CTE after Woodbands flow 12 exit in the curre have 24 was raining heavily. I shouldown and other to traffic fam ahead. Subdenly a car (SMM 18176 of the behand collision states the rear perform of my vehicle. After the collision; another lorry (GBB 68582) then collided into the said car collision; another lorry (GBB 68582) then collided into the said car	E 3499 C) along SLE towned CTE after Woodlands flow from and the centre lane. It was rainting heavily. I should have and the centre lane from ahead Syddendy a car (SMM 1817G) and behind collided bate the rear portion of my vehicle. After the liberary another larry (GBB 68562) then collided into the said car.	scribe Circumstance	34/08/2021 at	@ 0820 48,	I was trav	elling in my vehicle
the centre line. It was raining heavily. I special are the centre of the same ahead. Subderly a car (SAM 18176) the stand collided boto the rear portion of my which. After the stand collision; another lorry (GBB 68582) then collided onto the sand car collision; another lorry anothe	the centre lane. 2 t uses raining heavily. I show about 1876) sed due to traffic fam ahead. Subardy a car (Smm 18176) behind collided bads the rein portion for my which. After the liston; another long (GBB 68562) then collided into the said car.	100 2409 ()	along SLE town	rde CTE aft.	er Woodland	Ave 12 with
Physical due to traffic can ahead. Subdoutly la car (Smith Deband collided bade the rear portion of my which. After the collision; another long (G.88 68582) then collided onto the soil car collision.	pel due to troffe fan ahead. Stillderly fa car (Smith) he behind collided bade the rest portion of my vehicle. After the lesion; another long (G88 68562) then collided onto the said car.	The state	Ane . 2+	was rainting	heavily	1 5/00x100000 and
appear area collided bads the new portion of my venice. He had collision; another long (GBB 68582) then collided onto the said car	behad collided bodo the rear portion for my vehicle. Here the search car. Illision; another long (G.88 62562) then collided anto the search car.	on the court	traffic ram	ahead. Side	Idealy pla	car (Sministra)
official is another long (GBB 68562) then collided into the said the	Mason; another long (G88 68562) then collected into the said our.	offer laboration	alleded date the	- rear portio	a lot my	refreche . After the
		aller anoth	er lorry (GBB	68562) then	colleded on	to the said car
		Collegion ! minin				
				The second second		
		ST THE PART OF THE				
				and the same		

# Declaration

MAN declare the lovegoing particulars are true in every respect

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre

Personnel

















