


REG. BY: Thevan | REF: Ntac

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 3 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHA3778U Yr Regn: 28/4/16
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Hyundai 110 c.c. 1685
 Colour: blue A/C: Insured / Std / NI / NA
 Sp. Reading: 445330 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KMHLB41UM64087873
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / SRM / STD A/Rim or _____
 Tyre Size: F: 205/60R16
 R: 205/60R16
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake

Front	Rear
R/Bal. <u>5</u> mm	R/Bal. <u>5</u> mm
L/Bal. <u>5</u> mm	L/Bal. <u>5</u> mm
D.O.A. <u>23/8/21</u>	D.O.I. <u>24/8/21 1530</u>

 Survey held at Comfort
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof/Top or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	rebate: 26546

Date/Time File Pass to? : Prelim. Report
 : Final Report
 Date/Time File Return to? _____
 Report Form No: _____
 Date/Time File Return to: _____

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: Site Insp (\$ _____)
 Interview (\$ _____)
 Tech. Invs (\$ _____)
 Wash and (\$ _____)
 Survey Fee: _____
 Transportation: _____
 S + RS: \$ _____
 Final: _____
 Other: _____
 TOTAL: _____

L/S Reg Date: 28-04-2016


COMFORT TRANSPORTATION PTE LTD
REPAIR ESTIMATE

Vehicle No. : SHA3778U
Make : HYUNDAI
Model : I-40

Date: 23/08/2021
Insurance: NTUC
MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount	
				\$1,106.00	Def
1	REAR BUMPER COVER			\$22.00	✓ nec
1	REAR BUMPER CLIPS			\$428.40	?
1	REAR BUMPER REINFORCEMENT			\$119.50	?
1	REAR BUMPER SPONGE			\$321.20	?
1	RR BUMPER REINFORCEMENT BRACKET LH RH		\$160.60	\$2,174.90	✓ DD
1	BOOTLID			\$63.10	✓ nec
1	BOOTLID 'H' EMBLEM			\$52.40	✓ nec
1	BOOTLID CRDI PLATE			\$85.00	✓ nec
1	BOOTLID MOULDING			\$67.90	✓ nec
1	BOOTLID I40 EMBLEM				
	SUB TOTAL			\$4,440.40	
	LESS 20%			\$888.08	
	DISCOUNTED TOTAL			\$3,552.32	
				\$60.00	Nett ✓
	1 BOOTLID COMFORT LOGO & TEL NO. STICKER			\$60.00	Nett
	Labour Charge			\$600.00	420
	PANEL BEATING			\$600.00	420 500
	SPRAY PAINTING CHARGE			\$60.00	30
	REMOVE/REFIX REVERSE SENSOR				
	TOTAL LABOUR			\$1,260.00	
	ESTIMATE TOTAL			\$4,872.32	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Theran LHK 24/8/21 ~~1530~~
82235769 theran@lkk auto.com
3clays w/p 
L/S after repair photos

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHA3778U
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Aug 2021
Vehicle Make:	HYUNDAI
Vehicle Model:	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	D4FDGU613767
Chassis No.:	KMHLB41UMGU087873
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$20,239.00
Original Registration Date:	28 Apr 2016
First Registration Date:	28 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$20,335.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Apr 2024
PARF Rebate Amount:	\$14,234.00
Intended COE Rebate Details	
COE Expiry Date:	27 Apr 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$36,862.00
COE Rebate Amount:	\$12,312.00
Total Rebate Amount:	\$26,546.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 25 Aug 2021

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	24/08/2021 10:41 (SGT)
Date of Accident	23/08/2021 09:15 (SGT)
Exact Location of Accident	MCE, Singapore
Additional Location Information	TOWARDS KEPPEL
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA3778U
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXX821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-98368883
Alternative Phone No	(Office) +65-65508768

VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	I40
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1685

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdPartyFireTheft
Fleet Policy	Yes
Policy Number	VFX/P2419138
Cover Note Number	-

DRIVER

Name of Driver	LIM EE TEE
NRIC No	SXXXX448D

Describe Circumstances of the Accident

ON 23/08/2021 AT ABOUT 0915HRS I WAS DRIVING MY VEHICLE A SHA3778U ON THE 2ND LANE OF MCE TOWARDS KEPPEL. AN UNKNOWN VEHICLE ON MY LEFT HONK ME. I DO NOT KNOW WHAT HAPPENED SO I SLOWED WHEN VEHICLE B PC1303P REAR ENDED MY VEHICLE A. I THEN MOVE TO THE LEFT ROAD SHOULDER AND STOP MY VEHICLE A. VEHICLE B STOP ON THE 2ND LANE AND GOT DOWN. HE THEN SHOUTED SOMETHING AND THEN HE LEFT THE SCENE. NO ONE WAS INJURED. NO SCENE PHOTOS AND NO PARTICULARS EXCHANGED

Declaration

I/We declare the foregoing particulars are true in every respect.

 Policyholder's Signature / Date & Time

 Driver's Signature (If driver is not the policyholder) / Date & Time

 Witnessed by Reporting Centre Personnel *Kyari Yong*