



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT                                                                     |                                                                                                                                                                                                                                                                                                                                               |                                                                                           |                                                             |                                                                                       |
|--------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|-------------------------------------------------------------|---------------------------------------------------------------------------------------|
| AXA INSURANCE PTE LTD<br>8 SHENTON WAY #24-01 AXA TOWER<br>SINGAPORE 068811<br>ATTN: CHEN XINYOU |                                                                                                                                                                                                                                                                                                                                               |                                                                                           | Ref: CS3/ASM21008939/Gvce2<br>Date: 01/09/2021<br>Code: ASM |                                                                                       |
| 1. Policy Particulars :- (THIRD PARTY CLAIM)                                                     |                                                                                                                                                                                                                                                                                                                                               |                                                                                           |                                                             |                                                                                       |
|                                                                                                  | Insured Veh.                                                                                                                                                                                                                                                                                                                                  | SHC 7034X                                                                                 | Veh. Inspected                                              | XE 3058D                                                                              |
|                                                                                                  | Policy No.                                                                                                                                                                                                                                                                                                                                    | VFX/P2419140                                                                              | Coverage (\$)                                               | 0.00                                                                                  |
|                                                                                                  | Claim No.                                                                                                                                                                                                                                                                                                                                     | S1M03GBW                                                                                  | Excess (\$)                                                 | 0.00                                                                                  |
|                                                                                                  | Assign From                                                                                                                                                                                                                                                                                                                                   | CHEN XINYOU                                                                               | Assign Date                                                 | 25/08/2021                                                                            |
| 2. Vehicle Particulars & Condition                                                               |                                                                                                                                                                                                                                                                                                                                               |                                                                                           |                                                             |                                                                                       |
|                                                                                                  | Make & Model                                                                                                                                                                                                                                                                                                                                  | HINO FS1EKMD-KAS                                                                          | c.c                                                         | 12913                                                                                 |
|                                                                                                  | Engine No.                                                                                                                                                                                                                                                                                                                                    | HIDDEN                                                                                    | Year of Reg.                                                | 2017                                                                                  |
|                                                                                                  | Chassis No.                                                                                                                                                                                                                                                                                                                                   | FS1EKM10032                                                                               | Colour                                                      | WHITE                                                                                 |
|                                                                                                  | Odometer                                                                                                                                                                                                                                                                                                                                      | -                                                                                         | Steering                                                    | IN ORDER                                                                              |
|                                                                                                  | Brakes                                                                                                                                                                                                                                                                                                                                        | IN ORDER                                                                                  | Modification                                                | NIL                                                                                   |
|                                                                                                  | General                                                                                                                                                                                                                                                                                                                                       | GOOD                                                                                      |                                                             |                                                                                       |
| 3. Conditions of Tyres                                                                           |                                                                                                                                                                                                                                                                                                                                               |                                                                                           |                                                             |                                                                                       |
|                                                                                                  |                                                                                                                                                                                                                                                                                                                                               | Size                                                                                      | Make                                                        | Balance                                                                               |
|                                                                                                  | R/H Front Tyre                                                                                                                                                                                                                                                                                                                                | 295/80 R22.5                                                                              | FALKEN                                                      | 6 mm                                                                                  |
|                                                                                                  | L/H Front Tyre                                                                                                                                                                                                                                                                                                                                | 295/80 R22.5                                                                              | FALKEN                                                      | 6 mm                                                                                  |
|                                                                                                  | R/H Rear Tyre                                                                                                                                                                                                                                                                                                                                 | 295/80 R22.5 (D/D)                                                                        | DOUBLESTAR                                                  | 6/6/6/6 mm                                                                            |
|                                                                                                  | L/H Rear Tyre                                                                                                                                                                                                                                                                                                                                 | 295/80 R22.5 (D/D)                                                                        | DOUBLESTAR                                                  | 6/6/6/6 mm                                                                            |
| 4. Description of Damages                                                                        |                                                                                                                                                                                                                                                                                                                                               |                                                                                           |                                                             |                                                                                       |
|                                                                                                  | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.                                                                                                                                                                                                                                                                                            |                                                                                           |                                                             |  |
| 5. General Information                                                                           |                                                                                                                                                                                                                                                                                                                                               |                                                                                           |                                                             |                                                                                       |
|                                                                                                  | Accident Date                                                                                                                                                                                                                                                                                                                                 | 21/08/2021                                                                                | Inspect Date / Time                                         | 26/08/2021 ( 12:30 PM )                                                               |
|                                                                                                  | Survey held at                                                                                                                                                                                                                                                                                                                                | ENG SOON HUAT ENGINEERING WORKS<br>BLK 1003 EUNOS AVE 8# 01-55 EUNOS IND ESTATES S 409498 |                                                             |                                                                                       |
| 5a. Remarks                                                                                      |                                                                                                                                                                                                                                                                                                                                               |                                                                                           |                                                             |                                                                                       |
|                                                                                                  | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.<br>THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.<br>D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$20,000-\$30,000 |                                                                                           |                                                             |                                                                                       |
| 5b. Estimate Days of Repair                                                                      |                                                                                                                                                                                                                                                                                                                                               |                                                                                           |                                                             |                                                                                       |
|                                                                                                  | ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                                                                                                                                                                           |                                                                                           | 2 Working Days                                              |                                                                                       |

Report Ref No. CS3/ASM21008939/Gvce2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.