



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH			Ref: CC4/ASM21008951/Apa3q2 Date: 20/12/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XD 6934K	Veh. Inspected	SLX 8365B
	Policy No.	GA536882	Coverage (\$)	0.00
	Claim No.	S1M03GC2	Excess (\$)	0.00
	Assign From		Assign Date	25/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE HYBRID	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	GP71121429	Colour	RED
	Odometer	210127 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/60 R15	MICHELIN	6 mm
	L/H Front Tyre	195/60 R15	MICHELIN	6 mm
	R/H Rear Tyre	195/60 R15	MICHELIN	6 mm
	L/H Rear Tyre	195/60 R15	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND O/S UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/08/2021	Inspection Date	25/08/2021
	Survey held at	SM AUTOMOTIVE BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days