



# Service Request Details

Claim

S1M03GE7

Reference

CS/ASM21008955/c 

Loss Date

23 August 2021

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

25 Aug 2021 9:19:16 AM

Request Date

25 August 2021

Due Date

1 September 2021

Services

Pre-Repair Survey

Actions

Next Step

Agree to perform service

Decline Work



Vehicle Information

Incident Vehicle Registration #  
SKK7580H

Make  
TPVD BMW

Model  
116i

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE, 575717, Singapore  
65551188

Claim Handler

CHAN Kian Chuan  
68805444  
kianchuan.chan@axa.com.sg

Additional Instructions

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

New Message

TYPE



SENT

25/8/21 5:34 PM



BODY

Please be informed that the said vehicle can be in...

TYPE

?

SENT25/8/21 5:29 PM

FROMLKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT**S1M03GE7**

BODYHi Kian Chuan,may i have workshop detail? Thank yo...