

REF: CS/CTI21008956/Guc

Special Instruction:

From (Person): IRENE TAY of CTI ASSIGNMENT (Office)  
Estimated Cost: \_\_\_\_\_ Date/Time: 25.08.2021  
Bill to: \_\_\_\_\_

LS : \$ 18,900

*Third Parties:*

Claimant:

Surveyor:

Workshop: MJE MOTOR

OD/TP Re-inspection / Evaluation

To inspect Vehicle No: SLM 8051P Insured: GBJ 5276L

at Workshop m/s **MJE MOTOR**

Tel:

of ~~BLK 7 SIN MING IND EST SEC C #01-96 SINGAPORE 575642~~

Policy No: \_\_\_\_\_ Claim No: SNM21D203540/C03

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 23/06/2021  
(Client's Record)

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT \_\_\_\_\_

Date/Time: 12/10/2021 Confirmed with \_\_\_\_\_ Final Fig \_\_\_\_\_, \_\_\_\_ days (Red \$ \_\_\_\_/\_\_\_\_%; Original \_\_\_\_ days)

Date/Time: 13/10/2021 Submit Final Fig \$12200, 14 days (Red \$6700 / 35 %; Original 21 days)

[illegible]

**Para(1) : Parts found not replaced (To highlight *R* or *UB*, *LR*, *Etc*)**

**Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)**

Para(3) : Nett Value

Market Value : \_\_\_\_\_

Salvage Value : \_\_\_\_\_

Nett Value : \_\_\_\_\_

Inspected/  
Evaluated by:

*Fee Charged:*

Basic &amp; Add

Transport

## Photos

Others

Total

Date: \_\_\_\_\_

| Date/Time |           | File Pass to |              | File Return to |           | Total          |
|-----------|-----------|--------------|--------------|----------------|-----------|----------------|
| 1)        | Date/Time |              | File Pass to | 2)             | Date/Time | File Return to |
| 3)        | Date/Time |              | File Pass to | 4)             | Date/Time | File Return to |
| 5)        | Date/Time |              | File Pass to | 6)             | Date/Time | File Return to |