

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SCG 6128D
at Workshop m/s TAN CHONG
of 911, BUKIT TIMAH RD
Insured: FCI
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)
Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
-----	-----

Bal. or Market Value: 67K
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: SCG 6128D Yr Regn: 2017 / MAY
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: NISSAN QASHQAI 2.0 CVT c.c. 1997
Colour: GREY A/C: Insured / Std / NI / NA
Sp.Reading: 89855 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: SNFBAJUW1945450
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or _____
Brake: Inorder / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 225/452R19
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 20/08/21 D.O.I. 31/08/21
Survey held at TAN CHONG
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair limit - 21K</u>

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐: Prell. Report
☐: Final Report

Days Of Repair: _____
Resurvey No. of Trip: _____

Add Fee: ☐: Site Insp (\$ _____)
☐: Interview (\$ _____)
☐: Tech. Invs (\$ _____)
☐: Weekend (\$ _____)

Survey Fee: _____
Transportation: _____
S + RS _____ SI
Photos
Others
TOTAL

Report Format : _____
Lump Sum / I.B.I: (\$ _____)

TAN CHONG MOTOR SALES PTE. LTD.

911, BUKIT TIMAH ROAD

SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0216/2021
DATE : 25-AUG-2021

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : MR TAN YOKE HONG (CHEN YUFENG)
ADDRESS : 2B HONG SAN WALK
#13-08
S(689048)
TELEPHONE NO : 97822985

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-GBF7399Z
VEHICLE NO : SCG6128D
MODEL CODE : FDRARBZJ11EWAFJJ-
MODEL/YEAR : NISSAN QASHQAI 2.0
ENGINE NO : MR20457488W-J11WW
CHASSIS NO : SJNFBAJ11U1945450
MILEAGE : 1 KM
DATE IN : 25/08/2021
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 20/08/2021

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

CAR IN WORKSHOP / CAR NOT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : lawrenceteo@tanchong.com

H / P : 94568832 FAX : 64697472

16/8/21
25/08/2021

L1K

APR

10/08/21
30/08

20/08

31/08

10/09

APPT

WAITING

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SCG6128D

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RITCAM	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	120.00	/
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 02	240.00	120
3	RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	/
4	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 02	200.00	100
5	SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	/
6	UG10	RENEW ^{REAR} FRONT WINDSHIELD GLASS ASSY.	240.00	/
7	ZZ/001	REPAIR END PANEL, LH REAR FENDER AND RENEW REAR BUMPER, TAILGATE @ 390	1950.00	1170
8	ZZ/002	S/PAINT REAR BUMPER (2 TONE), TAILGATE, END PANEL, LH REAR FENDER @ 250 x 3 + 100	1350.00	850
9	ZZ/003	TRANSFER TAILGATE MECHNICAL PARTS TO NEW DOOR	80.00	/
10	ZZ/004	R/I REAR DVR TO ASSSIT REPAIR	120.00	/
11	ZZ/005	CHECK LIGHTING	48.00	/
TOTAL LABOUR CHARGES			4608.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SCG6128D

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 EMBLEM <i>to be</i>	90892-4EA0A	94.40			
2 EMBLEM-REAR <i>X</i>	90890-4EA0A	64.90			
3 A LOCK LIFT <i>X</i>	90502-4EA1B	173.20			
4 RUBBER-DUM <i>re</i>	G2716-89900	63.80			
5 REAR W/SCREEN SEALANT <i>re</i>	SEALANT - 4			80.00	
6 GLASS-TAIL GATE <i>re / phoh?</i>	90300-4EA0D	1089.00			
7 DOOR BACK <i>bt</i>	K0100-4EAAC	3368.90			
8 BRACKET-BUMPER RH <i>?</i>	85220-4EA0A	38.90			
9 BRACKET-BUMPER LH <i>?</i>	85221-4EA0A	38.90			
10 RETAINER-BUMPER RH <i>?</i>	79184-4EA0A	25.70			
11 RETAINER-BUMPER LH <i>?</i>	79185-4EA0A	25.70			
12 CANOE RIVET BUMPER \$7.10 EA X 02 <i>re</i>	76882-0M000	14.20			
13 CLIP BUMPER \$8.00 EA X 03 <i>re</i>	85284-JD00A	24.00			
14 GROMMET BUMPER \$2.70 EA X 04 <i>re</i>	63846-5V000	10.80			
15 CLIP BUMPER \$1.30 EA X 04 <i>re</i>	01553-05933	5.20			
16 GROMMET BUMPER \$2.40 EA X 02 <i>re</i>	01281-00111			4.80	
17 STAY ASSY-REAR RH <i>?</i>	H5210-4EAMA	141.00			
18 STAY ASSY-REAR LH <i>?</i>	H5211-4EAMA	141.00			
19 REINF-BUMPER RR <i>?</i>	H5030-4EAMA	691.50			
20 ENERGY ABSORBER <i>?</i>	85090-4EA0B	155.60			
21 FINISHER-REAR BUMPER TOW <i>?</i>	85071-4EA0A	18.80			
22 FASCIA-RR BUMP <i>de</i>	85022-4EA0H	876.40			
23 CLIP END PANEL \$1.30 EA X 02 <i>?</i>	01553-05323	2.60			
24 CLIP-FINISHER \$1.30 EA X 04 <i>?</i>	01554-00181	5.20			
25 PLATE LUGGAGE REAR <i>?</i>	84992-4EA0B	63.90			

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SCG6128D

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
26	FENDER RH REAR ARC ?	93828-4EA0A	540.50		
27	FENDER LH REAR ARC ?	93829-4EA0A	540.50		
28	ORNAMENT ASSY RH ?	26560-JJ90A	61.90		
29	ORNAMENT ASSY LH ?	26565-JJ90A	61.90		
30	CLIP ANTENA \$3.80 EA X 02 X	01553-89900		7.60	
31	ANTENNA-SMART KEYLESS ?	285E5-JK60A	53.50		
32	SUNDRIES	NPN		20	100.00
SUB TOTAL			8391.90	7.60	184.80
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1678.38	2.28	0.00
GRAND TOTAL			6713.52	5.32	184.80
OVERALL TOTAL			6903.64		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SCG6128D

TOTAL LABOUR CHARGES	4608.00
TOTAL SPARE PARTS CHARGES	6903.64
GRAND TOTAL	11511.64 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Rasul - 4p 90070068
SURVEYED DATE	:	31/08/21 @ 1030
AUTHORIZED DATE	:	5 days
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	Resury before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8/c.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	21/08/2021 01:16 (SGT)
Date of Accident	20/08/2021 06:48 (SGT)
Exact Location of Accident	396 Upper Bukit Timah Road, The Rail Mall, Singapore 678048
Additional Location Information	Upper Bukit Timah rd towards railway mall
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCG6128D
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN YOKE HONG
NRIC No	SXXXX721C
Email Address	pokodoy@gmail.com
Mobile Phone No	(Phone) +65-97822985
Alternative Phone No	+65-97822985

VEHICLE PARTICULARS

Manufacturer	Nissan
Model	Qashqai
Variant	2.0
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1997

INSURANCE COMPANY

Name of Insurance Company	Aviva Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	10838041
Cover Note Number	NA

DRIVER

Name of Driver	TAN YOKE HONG
NRIC No	SXXXX721C



Date Of Birth	20/03/1971
Occupation	Indoor
Date Of Driving Pass	20/12/1990
Driving experience	30 YEARS AND 8 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97822985
Alt. Phone Number	+65-97822985
Email Address	pokodoy@gmail.com
Address	2B Hong San Walk
Address complement	#13-08
Postcode	689048
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	Tan Jing yi
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

On 20/08/21 I SCG6128D was driving along Upper Bukit Timah rd near Bukit Panjang MRT towards Railway mall on the most right lane with my passenger. Just after passing by the shell petrol station (772 Upper Bukit Timah rd) , due to the traffic condition, my car came to a complete stop outside the yellow junction box. Suddenly the 3rd party GBF7339Z did not keep a proper look out on the road condition and rear end directly into my car. The impact has cause my passenger and myself great discomfort in our neck area. I managed to take take some photos and exchange particulars with the 3rd party and I also had an in car camera footage of the scene

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	UPLOADED INTO FILEZILLA
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF7399Z
Vehicle Manufacturer	Nissan

Vehicle Model	Nv200
Vehicle Variant	-
Vehicle Colour	Gray
Vehicle Category	Commercial vehicle
Name of Driver	GOVINDARASU SENGUTTUVAN
Work Permit No	GXXXX701N
Contact Number	(Phone) +65-94867998
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
 MUHAMMAD SUMARDI BIN MOHD AFFANDI
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

ACCIDENT DIAGRAM


Ver 307042021

UDD - Bukit Timah RD
TOWARDS BOLLING MILL



A SCG 6128 D

B GBF 7399 Z


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

VERIFIED BY AJAX MARS (ARC)
REPORTING OFFICER
MUHAMMAD SUMARDI BIN MOHD AFFANDI

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

REFER TO ATTACHED ACCIDENT DIAGRAM

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 20/08/21 I SCG6128D was driving along Upper Bukit Timah rd near Bukit Panjang MRT towards Railway mall on the most right lane with my passenger. Just after passing by the shell petrol station (772 Upper Bukit) Tj ET BT /CLIPFO outside the yellow junction box. Suddenly the 3rd party GBF7339Z did not keep a proper look out on the road condition and rear end directly into my car. The impact has cause my passenger and myself great discomfort in our neck area. I managed to take take some photos and exchange particulars with the 3rd party and I also had an in car camera footage of the scene

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

VERIFY BY AJAX MARS (ARC)

REPORTING OFFICER

MUHAMMAD SUMARDI BIN MOHD AFFANDI

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	721C
Vehicle No.:	SCG6128D
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Sep 2021
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 2.0 CVT ABS D/AIRBAG 2WD 5DR S/R
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	MR20457488W
Chassis No.:	SJNFBAJ11U1945450
Maximum Power Output:	106.0 kW (142 bhp)
Open Market Value:	\$19,507.00
Original Registration Date:	30 May 2017
First Registration Date:	30 May 2017
Transfer Count:	0
Actual ARF Paid:	\$19,507.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 May 2027
PARF Rebate Amount:	\$14,630.00
COE Expiry Date:	29 May 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,001.00
COE Rebate Amount:	\$30,432.00
Total Rebate Amount:	\$45,062.00

The information contained herein is correct as at 01 Sep 2021

OK

Nissan Qashqai 2.0A

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

PRIME MOTOR & LEASING



(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)

• PRIME CAR RENTAL & TAXI SERVICES PTE LTD • SECTION CREDIT & MOTOR LEASING PTE LTD • BEST PETROL AND DIESEL SUPPLY PTE LTD • BEST ELECTRICITY SUPPLY PTE LTD

Price **\$63,800**

Depreciation ?	\$10,100 /yr View models with similar depre	Reg Date	05-Jan-2017 (5yrs 4mths 3days COE left)
-----------------------	--	-----------------	--

Mileage	69,340 km (14.9k /yr)	Manufactured ?	2016
----------------	-----------------------	-----------------------	------

Road Tax ?	\$1,210 /yr	Transmission	Auto
-------------------	-------------	---------------------	------

Dereg Value ?	\$39,450 as of today (change)	OMV ?	\$19,653
----------------------	-------------------------------	--------------	----------

COE ?	\$46,229	ARF ?	\$19,653
--------------	----------	--------------	----------

Engine Cap	1,997 cc	Power	106.0 kW (142 bhp)
-------------------	----------	--------------	--------------------

Curb Weight ?	1,379 kg	No. of Owners ?	2
----------------------	----------	------------------------	---