



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:YVONNE ANG			Ref: CC4/ASM21009005/Ara3q2 Date: 19/11/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 6585P	Veh. Inspected	SDY 1311S
	Policy No.	P2419138	Coverage (\$)	0.00
	Claim No.	S1M03GI1	Excess (\$)	0.00
	Assign From		Assign Date	26/08/2021
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 3 HB	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JM6BM44A8G0324691	Colour	BLACK
	Odometer	125447 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	HANKOOK	6 mm
	L/H Front Tyre	205/60 R16	HANKOOK	6 mm
	R/H Rear Tyre	205/60 R16	HANKOOK	6 mm
	L/H Rear Tyre	205/60 R16	HANKOOK	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/08/2021	Inspection Date	27/08/2021
	Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	