



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: ANG YVONNE		Ref: CS/ASM21009027/Kvce2 Date: 07/09/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 7531C	Veh. Inspected	GBE 5200G
Policy No.	VFX/P2419140	Coverage (\$)	0.00
Claim No.	S1M03GK2	Excess (\$)	0.00
Assign From	ANG YVONNE	Assign Date	27/08/2021
2. Vehicle Particulars & Condition			
Make & Model	NISSAN CABSTAR	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JN1SC2F24Z0857975	Colour	SILVER
Odometer	208414 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15X8	FALKEN	8 mm
L/H Front Tyre	195 R15X8	FALKEN	8 mm
R/H Rear Tyre	155 R12X8 (D)	ARIVO	4/4 mm
L/H Rear Tyre	155 R12X8 (D)	ARIVO	4/4 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/08/2021	Inspection Date	27/08/2021
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	