

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS3/SMO21009033/Atf3e2	
	50 RAFFLES PLAC TOWER SINGAPO	CE #03-03 SINGAPORE LAND PRE 048623		Date:	24/11/2021	
				Code:	SMO	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SKS 391R	Veh. Inspected	t	SMW 7483T	
	Policy No.	D21MTPV01004088	Coverage (\$)		0.00	
	Claim No.	CMTD2102520/RUC	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		27/08/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	B.M.W. Z4	c.c		2171	
	Engine No.	HIDDEN	Year of Reg.		2006	
	Chassis No.	WBABT12050LR02142	Colour		BLACK	
	Odometer	199184 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/40 R18	HAIDA		6 mm	
	L/H Front Tyre	225/40 R18	HAIDA		6 mm	
	R/H Rear Tyre	225/40 R18	HAIDA		6 mm	
	L/H Rear Tyre	225/40 R18	HAIDA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.					
5.	General Information					
	Accident Date	20/08/2021	Inspect Date /	Time	30/08/2021 ( 01:50 PM )	
	Survey held at	EQUATOR BROTHERHOOD				
		25 KAKI BUKIT ROAD 4 #03-19 SYNERGY @KB SINGAPORE 417800				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000					
5b.		Estimate Days of Repair				
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				

Report Ref No. CS3/SMO21009033/Atf3e2

Inspected By

ADRIAN LING WAI PING

K.K.LAU CPT(RET)

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.