

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref	: CS/AGI21009047/Uqf3n2	
	(BUDGET DIRECT 190 CLEMENCEA SINGAPORE SHO 239924		Dat	e: 29/09/2021	
			Cod	de: AGI	
1.					
	Insured Veh.	SJX 7507P	Veh. Inspected	SMJ 7027X	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10011434/HA	Excess (\$)	0.00	
	Assign From	FRAUELINE KHOO	Assign Date	29/08/2021	
2. Vehicle Particulars & Condition					
	Make & Model	KIA CARENS DIESEL (A)	c.c	1685	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	KNAHU815VJ7211029	Colour	RED	
	Odometer	275437 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/55 R16	MOZZO	6 mm	
	L/H Front Tyre	205/55 R16	MOZZO	6 mm	
	R/H Rear Tyre	205/55 R16	MOZZO	6 mm	
	L/H Rear Tyre	205/55 R16	MOZZO	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	26/08/2021	Inspection Date	30/08/2021	
	Survey held at	TAN LIM MOTOR PTE LTD	-		
		NO.1 DEFU LANE 6 SINGAPORE 539365			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: