ASS. REC. BY: Steve REF: CS3/ASM21009962/Etc

## ASSIGNMENT

From: PRS Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

| N/S | O/S |
|---|---|
| | |

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

SIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Sum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: FBN4542D Yr Regn: 4/12/18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Texi / Prime Mover / Truck / Trailer or

Make: Honda CB190X c.c 184.4

Colour: Silver A/C: Insured / Std / Nil / N

Sp.Reading: 32378 T/Radio: Insured / Std / Nil / N

Eng/No:

C/No: LWBPCL1A1H1005573

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Locked / Burnt or

Brake: Inorder / Jammed / Locked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110/70R17

R: 130/70R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

| Front | | Rear | |
|---|---|---|---|
| R/Bal. | 4 mm | R/Bal. | 4 mm |
| L/Bal. | mm | L/Bal. | mm |
| D.O.A. | 13/6/21 | D.O.I. | 30/8/21 |

Survey held at Dynasty Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

| Date / Time | Action / Instruction |
|---|---|
| | MV - 8000 repair range 3K - 4K |
| | 3 repair days |

Date/Time, File Ross to: : Proll. Report

: Final Report

Date/Time, File Return to:

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp ($ )

: Interview ($ )

: Tech. Inve ($ )

: Weekend ($ )

Survey Fee:

Transportation:

$ + RS $

Photos

Others

TOTAL

Approved/Formal :

Date / U.P.I. / Cs