




## Service Request Details

### Claim

S1M03GPN

### Reference

CS3/ASM21009070/Vuc 

### Loss Date

28 August 2021

### Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

### Type of Loss

Third Party Vehicle Damage

### Report Date

29 Aug 2021 5:39:01 PM

### Request Date

30 August 2021

### Due Date

6 September 2021

### Services

Pre-Repair Survey

### Actions

---

#### Next Step

Agree to perform service

[Decline Work](#)



Vehicle Information

Incident Vehicle Registration #  
SGU7451S

Make  
TPVD

Model  
HONDA FIT

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE, 575717, Singapore  
65551188

Claim Handler

ANG Yvonne  
  
yvonne.ang@axa.com.sg  
Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message