



Service Request Details

Claim

S1M03GMA

Reference

CS/ASM21009077/Avc 

Loss Date

25 August 2021

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Report Date

27 Aug 2021 4:55:59 PM

Request Date

30 August 2021

Due Date

6 September 2021

Services

Pre-Repair Survey

Actions

Next Step

Agree to perform service

[Decline Work](#)



Vehicle Information

Incident Vehicle Registration #
SGW8668S

Make
TPVD HONDA

Model
MONILLIO

Service Address

, , ,

Primary Contact/Insured

LYU DESHENG @ LU DESHENG
6C ORANGE GROVE ROAD, #11-01, 258333, Singapore
98377111
LYUDESHENGLOUIS@GMAIL.COM

Claim Handler

OH Vale

vale.oh@axa.com.sg

Additional Instructions

Messages2

Invoices

History

Documents

Assessment

Metrics

Notes

New Message

TYPE	
SENT	30/8/21 2:41 PM



BODY

Dear Lynn,Noted with thanks. Yan.



TYPE



SENT

30/8/21 2:15 PM

FROM

KHONG Lynn

SUBJECT

TP WS ADDRESS

BODY

TK MOTOR WORKSHOP 1 Kaki Bukit Ave 6 #02-56 Aut...



TYPE



SENT

30/8/21 9:44 AM

FROM

LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT

S1M03GMA

BODY

Dear Vale, Thank you for the assignment. Please pr...

