

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969

Our Ref : 305484707  
Date : 30-8-21  
Time of Fax : \_\_\_\_\_

Via Fax : EMAIL  
Your Insured : 842 3688 B  
Date of Acc : 29-8-21

Attn: Motor Claims Department DLG

Dear Sirs

## SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH D 3679 G.

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

♦ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
♦ <u>Jumani Bin Masudin</u>	<u>Tel: 6214 8315 or HP: 9635 5305</u>
♦ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
♦ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006

} **jumanibm@cdge.com.sg**  
**Fax no. 6546 8156**

→ If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President  
Taxi Accident Repair

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305484707  
REGN NO : SHD3679G  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(G4)  
DATE OF REGN : 07.10.2016  
DATE/TIME IN : 30.08.2021 11:05  
ACCIDENT DATE : 29.08.2021

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001 04-01-0302-2292-G COVER FRONT BUMPER^ 1 499.90 25.00 374.92

0002 04-01-0302-2971-G SUPPORT FRONT BUMPER SIDE 1 82.30 25.00 61.72

SUB-TOTAL : 436.64

## JOB NATURE

0000 PB PANEL BEATING 400.00

0001 SP SPRAYPAINT CHARGE 300.00

SUB-TOTAL : 700.00

TOTAL : 1,136.64

MVA NAME &amp; SIGNATURE

DATE :

SURVEYOR NAME &amp; SIGNATURE

DATE :

AUTHORISED : YES / NO

Date/Time: 30.08.2021 15:03 Page : 1


Team: ARC Repair TP(CLSO)1 JOB CARD Sales Order: 4113557 JC NO.:305484707

OWNER	REGN NO.: SHD3679G	MILEAGE
AS COMFORT TRANSPORTATION PTE LTD	MAKE: TOYOTA	FUEL
OWNER NO. 7010045	MODEL	DATE/TIME IN
RESS 383 SIN MING DRIVE	PRIUS HYBRID(G4)30	08.2021 11:05
Singapore SINGAPORE 575717	YR OF MANU.	TARGET DATE
(R) 65508755 (O)	07.10.2016	
(P)	CHASSIS CODE	COMPLETION DATE/TIME:
	JTDKB3FU203533433	
COUNT CARD NO.		

JOB DESCRIPTION

Accident Date: 29.08.2021  
NATURE: 3P 29.08.2021

S/NO	LABOR CODE	DESCRIPTION
00000	PB	PANEL BEATING
000040	SP	SPRAYPAINT CHARGE



WORKED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR \_\_\_\_\_ CUSTOMER'S SIGNATURE \_\_\_\_\_

acknowledgement Slip	Exit Pass
No.: SHD3679G JU AIG	Vehicle No.: SHD3679G
Service Advisor _____	Name of Service Advisor _____
Signature/Date _____	Date _____
turned to Service Reception upon collection	To be kept by Security Guard