

ALG CLM

COMFORTDELGRO ENGINEERING PTE LTD

Date: 30.08.2021

LKK

REPAIR ESTIMATE

Time: 15:00:20

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305484707
REGN NO : SHD3679G
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 07.10.2016
DATE/TIME IN : 30.08.2021 11:05
ACCIDENT DATE : 29.08.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2292-G	COVER FRONT BUMPER^	1	499.90	25.00	374.92	cut
0002 04-01-0302-2971-G	SUPPORT FRONT BUMPER SIDE	1	82.30	25.00	61.72	cut
	LH Headlight					
					SUB-TOTAL	: 436.64

JOB NATURE

0000 PB	PANEL BEATING	400.00	350
0001 SP	SPRAYPAINT CHARGE	300.00	250
		SUB-TOTAL	: 700.00
		TOTAL	: 1,136.64

Jumani

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Approved by Repairer

Thavan 1600 30/8/21
Lkh
2 days wp
82235769
Thavan @ Lkh auto-lam
after repair photos