

ComfortDelGro Engineering Pte Ltd (Co.Reg.No 199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER:
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

Jumani

(Lhh) 48um

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	29/08/2021
Vehicle Reg. No.:	SHD3311S	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	27/07/2016
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	D4FDGU706883	Chassis No:	KMHLB41UMGU093155
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	4,630.02
Miscellaneous Items	11.00
Labour	1,330.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	5,971.02
+ GST 7.00% (\$\$)	417.97
Nett Amount (\$\$)	6,388.99

This claim is handled by: JUMANI BIN MASUDIN

Generated Using Merimen Claims and Estimation & Adjusting System

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Thuan Lhh

92235769

thuan@lhhauto.com

30/8/21 1730

L/S after repair photos

4 days wp

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 30 Aug 2021)**Parts:** 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHD3311S/30/08/2021 11:35**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ASSY	20.00	0.00	*1,106.00 FL/Cat
2	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL/nic
3	1		*REAR BUMPER SPONGE	20.00	0.00	*119.50 FL?
4	1		*REAR BUMPER REINFORCEMENT BEAM	20.00	0.00	*428.40 FL?
5	1		*REAR BUMPER REINFORCEMENT BRACKET RH	20.00	0.00	*160.60 FL?
6	1		*REAR BUMPER SIDE BRACKET RH	20.00	0.00	*35.60 FL/nic
7	1		*REAR BUMPER UNDER COVER	20.00	0.00	*288.00 FL/Cat
8	1		*REAR BUMPER REFLECTOR RH	20.00	0.00	*32.00 FL/cra
9	1		*REAR EXHAUST PIPE RH	20.00	0.00	*1,935.40 FLxr
10	1		*REAR EXHAUST PIPE CENTRE	20.00	0.00	*730.10 FLxr
11	1		*TAILLAMP ASSY RH	20.00	0.00	*697.80 FL/cra
12	1		*REAR BUMPER ADVERTISEMENT LOGO	0.00	0.00	*50.00 F/nic
13	1		*REVERSE SENSOR	0.00	0.00	*135.70 F/Cat

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	5,741.10
- List Item Discount on L Items (\$\$)	1,111.08
Total Parts (\$\$)	4,630.02

ComfortDelGro Engineering Pte Ltd/SHD3311S/30/08/2021 11:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No Qty Particulars

Miscellaneous Items

1 1 OD/TP Case (Insurer)

Amount

11.00

Sub Total (\$\$)

11.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 PANEL BEATING

560

2 SPRAYPAINT

New

600.00 ~~395~~

3 CHECK WIRING

New

600.00 500

4 REMOVE/REFIX REVERSE SENSOR

New

50.00 20

New

80.00 30

Gross Labour Cost (\$\$)

1,330.00

ComfortDelGro Engineering Pte Ltd/SHD3311S/30/08/2021 11:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Date/Time: 30.08.2021 11:17 Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 4113436

JO NO. 305484607


COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (O)

REGN NO: SHD3311S	MILEAGE
MAKE: HYUNDAI	FUEL E 1/2 F
MODEL I-40	DATE/TIME IN 30.08.2021 08:55
YR OF MANU. 27.07.2016	TARGET DATE
CHASSIS CODE KMHLB41UMGU093155	COMPLETION DATE/TIME

JOB DESCRIPTION

Accident Date: 29.08.2021
NATURE: 3P 29.08.2021

S/NO LABOR CODE DESCRIPTION



KEYED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Checklist Slip

Exit Pass

Vehicle No.: SHD3311S

JU TOKIO

Vehicle No.:

SHD3311S

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard