

Ref: FIC. BY: Thuan


Ref: CS3/ASm 2009/73/UTC

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD/TP/WS/TP RES/OD RES/EVA/INV/MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 2444k
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBR3214L Yr Regn: 21/4/170
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Yamaha Xmax 300 c.c. 300
 Colour: Silver A/C: _____ Insured / Std / NI / NA
 Sp. Reading: Not avail T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MT35H0844kko08670
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 130/70/15
 R: 130/70/15
BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. 14/8/21 D.O.I. 2/9/21
 Survey held at Quador brotherhood
 Des. of Damages: Fr / Rear / O/S / NIS / UIC / Roof/Top or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MV: <u>21/4/21</u>
	rebate: <u>3792</u>
	MV: <u>20208</u>
	rr: <u>4.5h - 5k</u>
	GIA INV. <u>WS</u>

Date/Time File Pass to?

☐ : Prelim. Report

1)

☐ : Final Report

Date/Time File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Wash and (\$ _____)

Survey Fee:

Transportation: _____

Finishes _____

Delivery _____

Total _____

Request Form:

Request Form / Request Form

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	647E
Vehicle Details	
Vehicle No.:	FBR3214L
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Sep 2021
Vehicle Make:	YAMAHA
Vehicle Model:	CZD300A / XMAX300
Primary Colour:	Silver
Manufacturing Year:	2019
Engine No.:	H336E0063682
Chassis No.:	MH3SH0844KK008670
Maximum Power Output:	-
Open Market Value:	\$4,581.00
Original Registration Date:	21 Apr 2020
First Registration Date:	21 Apr 2020
Transfer Count:	1
Actual ARF Paid:	\$688.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Apr 2030
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$4,401.00
COE Rebate Amount:	\$3,792.00
Total Rebate Amount:	\$3,792.00

The information contained herein is correct as at 08 Sep 2021

OK

dp. 233/m

avg \$m / 1/6

$$233 \times 116 = 27028$$
$$= 27k$$

$$27k - 3792 = 23208$$

Model	Yamaha Xmax 300
Engine Capacity	292cc
Classification	Class 2A
Registration Date	27/03/2020
COE Expiry Date	26/03/2030 (8 years 6 months left)
Mileage	1200km
No. of owners	1
Type of Vehicle	Scooters

SGD **\$23800**

Yamaha Xmax 300 For Sale.
 Not A Daily Ride.
 Selling With Nice Number Plate.

Close ^

Similar Bikes

View More



04/09/2021

Used Bike

★ C.S.T.K Pte Ltd

Yamaha Xmax 300

Very Low Mileage Yamaha Xmax ...

\$12555



03/09/2021

Used Bike

★ Direct Seller

Yamaha Xmax 300

Fully Stock Yamaha Xmax 300. ...

\$15800

