

ASS. REC. BY:

REF:

A/G / 21009173/ke

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

845k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGC 8543L

Yr Regn:

12, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Kis Forte K3

c.c

1591

Colour

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

71233

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNAIF X 411 MF 55 22351

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

27/8/21

D.O.I.

1/9/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

& 14

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

8/9 11:00 AM @ 52501 Carlow 6/10/21

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

1)

Date/Time, File Return to?

☐

: Final Report

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Withheld
C/Sup 85250/h
Primary After Pains
5days

To: **AIG Asia Pacific Insurance Pte Ltd**

Policy No: _____ Third Party

Date: **31.08.2021**

Accident Date : 27.08.2021

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Kia Forte" Reg. No. SGC6543L Claiming Against Your Insured Reg. No. SMR4332S			
1pc	Rear Bumper <i>688</i>		<i>Bur</i> 856.00 <i>✓</i>
12pcs	Rear Bumper Clips	4.50	<i>na</i> 54.00 <i>✓</i>
1pc	Rear Bumper Sponge		<i>Sn</i> 235.00 <i>X</i>
2pcs	Rear Bumper Brackets	39.00	<i>CMS</i> 78.00 <i>✓</i>
1pc	Rear Bumper Reinforcement <i>350</i>		<i>R</i> 434.00 <i>✓</i>
1pc	Rear Bumper Lower Lip		<i>Real Gr</i> 245.00 <i>✓</i>
2pcs	Rear Bumper Reflectors <i>@95.00</i>	132.00	<i>cut/scr</i> 264.00 <i>✓</i>
3pcs	Rear Bumper Lower Retainers	45.00	<i>CMS</i> 135.00 <i>✓</i>
1pc	Rear Bumper Auto Boot Sensor		<i>Sn</i> 125.00 <i>X</i>
1pc	Boot Emblem		<i>na</i> 43.00 <i>✓</i>
1pc	Boot Badge FORTE		<i>na</i> 42.00 <i>✓</i>
1pc	Boot Badge K3		<i>na</i> 39.00 <i>✓</i>
1pc	End Panel		<i>R</i> 335.00 <i>X</i>
1pc	End Panel Garnish		<i>my Div</i> 165.00 <i>✓</i>
1pc	Front Bumper <i>; 745.20</i>		<i>my CMS</i> 820.00 <i>✓</i>
10pcs	Front Bumper Clips	4.50	<i>na</i> 45.00 <i>✓</i>
1pc	Front Bumper Sponge		<i>CMS</i> 116.00 <i>✓</i>
1pc	Front Bumper Reinforcement <i>313</i>		<i>R</i> 423.00 <i>✓</i>
1pc	Front Bumper Number Plate Holder		<i>CMS</i> 47.00 <i>✓</i>
1pc	Front Bumper Center Air Grille		<i>na</i> 79.00 <i>✓</i>
1pc	Front Bumper Emblem		<i>na</i> 42.00 <i>✓</i>
1pc	Grille		<i>na</i> 324.00 <i>✓</i>
2pcs	Headlamp Assy (HID) <i>@1523.00</i>	<i>N/S my CMS</i> 1,850.00	3,700.00 <i>✓</i>
			8,646.00
	Less 10%		864.60
			7,781.40
	Rear Bumper Reverse Sensor		<i>Cut</i> 280.00 <i>SN</i>
	Boot Badge C&C		<i>na</i> 50.00 <i>SN</i>
	Front Number Plate		<i>R</i> 45.00 <i>SN</i>
	To Conduct Rear Electrical Check, Replace Reverse Sensors, Module, Rewiring etc.		120.00 <i>501</i>
	To Dismantle / Refit Trunk Compartment Boards & Trims		<i>na</i> 80.00 <i>X</i>
	To Supply End Panel Body Sealant		<i>na</i> 60.00 <i>X</i>
		C/F	8,416.40

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 31.08.2021

Accident Date : 27.08.2021

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Kia Forte" Reg. No. SGC6543L Claiming Against Your Insured Reg. No. SMR4332S		
		B/F	8,416.40
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		100.00
	To Conduct Front Electrical Check, Focus Headlamp		30.00
	Labour Charge - Panel Beating, Repairing Rear Chassis Member, Boot Lid, Floor Panel, Spare Tyre Panel, Front Support etc. Cnt, Weld End Panel and Parts Replacement		1,100.00
	To Respray Affected Areas (Big Veh)		1,000.00
		Total :	10,646.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: