

|   |        |      |             |
|---|--------|------|-------------|
| 1 | of 2 ? | 100% | Find   Next |
|---|--------|------|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|                                                                                                                                                                                                                                                  |                                                                          |                 |                           |  |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------|-----------------|---------------------------|--|
| <b>Affiliated to Federation Internationale Des Experts En Automobile</b>                                                                                                                                                                         |                                                                          |                 |                           |  |
| SOMPO INSURANCE SINGAPORE PL                                                                                                                                                                                                                     |                                                                          |                 | Ref: CS3/SMO21009204/Auf3 |  |
| 50 RAFFLES PLACE #03-03                                                                                                                                                                                                                          |                                                                          |                 | Date: 01/09/2021          |  |
| SINGAPORE LAND TOWERSINGAPORE 048623                                                                                                                                                                                                             |                                                                          |                 | Code: SMO                 |  |
| <b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>                                                                                                                                                                                              |                                                                          |                 |                           |  |
| Insured Veh.                                                                                                                                                                                                                                     | SLM 2268X                                                                | Veh. Inspected  | GBK 4061R                 |  |
| Policy No.                                                                                                                                                                                                                                       |                                                                          | Coverage (\$)   | 0.00                      |  |
| Claim No.                                                                                                                                                                                                                                        | CMTD2102627/LOR                                                          | Excess (\$)     | 0.00                      |  |
| Assign From                                                                                                                                                                                                                                      | GRACE TEO                                                                | Assign Date     | 01/09/2021                |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                                                                                    |                                                                          |                 |                           |  |
| Make & Model                                                                                                                                                                                                                                     |                                                                          | c.c             | 0                         |  |
| Engine No.                                                                                                                                                                                                                                       | HIDDEN                                                                   | Year of Reg.    |                           |  |
| Chassis No.                                                                                                                                                                                                                                      |                                                                          | Colour          |                           |  |
| Odometer                                                                                                                                                                                                                                         | -                                                                        | Steering        |                           |  |
| Brakes                                                                                                                                                                                                                                           |                                                                          | Modification    |                           |  |
| General                                                                                                                                                                                                                                          |                                                                          |                 |                           |  |
| <b>3. Conditions of Tyres</b>                                                                                                                                                                                                                    |                                                                          |                 |                           |  |
|                                                                                                                                                                                                                                                  | Size                                                                     | Make            | Balance                   |  |
| R/H Front Tyre                                                                                                                                                                                                                                   |                                                                          |                 | mm                        |  |
| L/H Front Tyre                                                                                                                                                                                                                                   |                                                                          |                 | mm                        |  |
| R/H Rear Tyre                                                                                                                                                                                                                                    |                                                                          |                 | mm                        |  |
| L/H Rear Tyre                                                                                                                                                                                                                                    |                                                                          |                 | mm                        |  |
| <b>4. Description of Damages</b>                                                                                                                                                                                                                 |                                                                          |                 |                           |  |
|                                                                                                                                                                                                                                                  |                                                                          |                 |                           |  |
| <b>5. General Information</b>                                                                                                                                                                                                                    |                                                                          |                 |                           |  |
| Accident Date                                                                                                                                                                                                                                    | 31/08/2021                                                               | Inspection Date | 02/09/2021                |  |
| Survey held at                                                                                                                                                                                                                                   | GARAGE 13 PTE LTD<br>8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE. |                 |                           |  |
| <b>5a. Remarks</b>                                                                                                                                                                                                                               |                                                                          |                 |                           |  |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.<br>THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |                                                                          |                 |                           |  |