


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 QD ☒ TP ☐ N/S ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV
 To Inspect Vehicle No: _____
 at Workshop m/s TEAMWORK GARAGE
 of _____
 Insured: _____
 Policy No: _____
 Claims No. NSV2100114/SG
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: \$170k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: EZ2525T Yr Regn: 25 Aug/2020
 Type ☒ M.Car ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: VOLVO S90 T5 MOMENTUM c.c 1969
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 19719 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: LVYPS10ADLP079893 *
 Gen. Cond: ☒ Good ☐ Fair / Poor / Burnt
 Steering: ☒ Inorder ☐ Jammed / Leaked / Burnt or
 Brake: ☒ Inorder ☐ Jammed / Leaked / Burnt or
 Modi: Nil ☒ S/Rim ☐ STD A/Rim or
 Tyre Size: F: 245/35R21
 R: 245/35R21
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR ☐ SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 02-09-2021
 Survey held at _____ W/S 12:30
 Des. of Damages: Frt / ☒ Rear ☐ O/S ☐ N/S ☐ U/C ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Guo Qiang finalised LS \$3650, 5 days. (Red \$18127.14, 83%)

Date/Time, File Pass to? ☐ : Preli. Report1) 12/05 Typist ☐ : Final Report

Date/Time, File Return to?

2) _____

Report Filed: TP

Long Quid / Red 3650

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Insp (\$ _____)☐ : A/Sel end (\$ _____)

Survey Fee:

Transportation:

S + RS. SI

Photos

Other:

TOTAL