


## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SMB327T  
Ref. No : BUS/08/16/7029  
Reg. Date : 23/08/2016  
Vehicle Type : BUS -12M  
Make : MAN  
Model : MAN  
Name of Driver : Anandan A/L Rengasamy  
Type of Accident : SIDE SWIPE  
Date / Time of Accident : 21/08/2016 03:03:00 PM  
Accident Reported Date / Time : 22/08/2016 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by : IDAC  
Vehicle is Towed Back? : No  
Towed Back Date/Time :  
Replacement Vehicle issued? : No  
Accident Repair Job Card No :  
Special Instruction to ARC,if any :

SMB327T - RIGHT VIEW MIRROR COVER SCRATCHES  
PC3500Z (TP) - LEFT WINDOW PANEL BROKEN

Prepared Date : 23/08/2016 05:19:15 PM



**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : Mileage : 0

Work Shop : Repair Completed Date / Time :

**Summary of Repair Estimates**

	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
Total Labout Charges :	265.00	0.00
Total Spray Painting Charges :	0.00	0.00
Total Material Charges :	878.40	896.33
Other Charges :	0.00	0.00
<b>TOTAL :</b>	<b>1,143.40</b>	<b>0.00</b>
<b>Lum Sum Total :</b>	<b>1,150.00</b>	<b>0.00</b>
No. of Repair Days :	1.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sing Off Date :	01/01/1900 12:00:00 AM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 13/08/2017 07:17:30 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	265.00	0.00
<b>Total Labour</b>	<b>265.00</b>	<b>0.00</b>

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Spray Painting &amp; Panel Beating</b>		

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
<b>Total Other Costs</b>		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
4001M01-ACCE467	RIGHT	6010161	FRONT VIEW MIRROR RH	1	1,244.90	10.00	1,120.41	Replace	Replace	No
TOTAL MATERIALS							1,120.41	1,120.41		
TOTAL MATERIALS(Discounted)							878.40	896.33		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									