

ASS. REC. BY:

TCUM

REF:

CC4/AIG21009221/B673

Jasper

ASSIGNMENT

From:

Date:

2/9/2021

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SBU1001G

at Workshop m/s

Dean Autopro

of

160 Sinking Dr #01-14

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

48,000/-

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SBU1001G

Yr Regn: 29/3/2016

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Corolla Altis

C.C 1598

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

31858

T/Radio: Insured / Std / NI / NA

Eng/No:

12RX551661

C/No:

MR053REH104545390

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size:

F: 205/55/16

R: 205/55/16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

2/9/2021

Survey held at

Dean Autopro

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Recommended car is \$ 4,200.00

TCUM Lim

27/9/2021

MV 48,000/-

PV 33,974/-

NV 14,026/-

TCUM Lim

2/9/2021

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format:

Lump Sum / L.B. / %

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SBU 1001 G**
 Model : Toyota Altis
 Year : 2015
 Chassis No : MR053REH104545390

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

| Nos. | PARTS | Qty | Unit S\$ | TOTAL S\$ |
|-------------------|------------------------------|-----|------------------|---------------------|
| 1 | Bootlid | 1 | \$ 1,093.00 | \$ 781.10 1,093.00 |
| 2 | Bootlid logo | 1 | \$ 85.50 | \$ 68.00 85.50 |
| 3 | Bootlid emblem 'COROLLA' | 1 | \$ 68.00 | \$ 32.00 68.00 |
| 4 | Bootlid emblem 'ALTIS' | 1 | \$ 65.37 | \$ 55.00 65.37 |
| 5 | Bootlid outer chrome garnish | 1 | \$ 415.60 | \$ 202.50 415.60 |
| 6 | Bootlid lamp LH BR, RH CUT | 2 | \$ 328.00 485.30 | \$ 656.00 970.60 |
| 7 | Bootlid inner lock | 1 | \$ 298.70 | \$ 298.70 |
| 8 | Bootlid inner lock striker | 1 | \$ 65.00 | \$ 65.00 |
| 9 | Bootlid inner trim board | 1 | \$ 352.80 | \$ 352.80 |
| 10 | Bootlid weatherstrip | 1 | \$ 298.60 | \$ 298.60 |
| 11 | Bootlid antenna sensor | 1 | \$ 218.40 | \$ 218.40 |
| 12 | Rear bumper | 1 | \$ 885.90 | \$ 639.80 885.90 |
| 13 | Rear bumper side retainer | 2 | \$ 65.00 110.20 | \$ 130.00 236.40 |
| 14 | Rear bumper inner sponge | 1 | \$ 141.80 | \$ 141.80 |
| 15 | Rear bumper reinforcement | 1 | \$ 487.30 | \$ 398.70 487.30 |
| 16 | Rear bumper side bracket | 2 | \$ 85.60 | \$ 171.20 |
| 17 | Rear bumper reflector | 2 | \$ 93.60 | \$ 187.20 |
| 18 | Rear end panel | 1 | \$ 762.10 | \$ 645.30 762.10 |
| 19 | Rear end panel top garnish | 1 | \$ 268.00 | \$ 185.99 268.00 |
| 20 | Rear fender inner trim board | 2 | \$ 458.00 | \$ 916.00 |
| 21 | Taillamp RH 1 | 2 | \$ 411.90 594.60 | \$ 411.90 1,189.20 |
| 22 | Taillamp lower bracket RH 1 | 2 | \$ 82.00 | \$ 82.00 164.00 |
| Parts Sub Total : | | | | \$ 4292.29 9,340.67 |
| 25% Discount : | | | | \$ 1073.07 2,335.17 |
| PARTS TOTAL : | | | | \$ 3219.22 7,005.50 |

| Nos. | SPECIAL NETT | Qty | Unit S\$ | TOTAL S\$ |
|----------------------|------------------------------------|-----|-----------|-----------------------------|
| 1 | Sundries | 1 | \$ 80.00 | \$ 80.00 |
| 2 | Bootlid sealant | 1 | \$ 100.00 | \$ 100.00 40.00 |
| 3 | Bootlid outer chrome garnish clips | 1 | \$ 50.00 | \$ 50.00 20.00 |
| 4 | Bootlid lamp seal | 2 | \$ 60.00 | \$ 120.00 60.00 |
| 5 | Bootlid lamp clips | 2 | \$ 50.00 | \$ 100.00 20.00 |
| 6 | Bootlid inner trim board clips | 1 | \$ 50.00 | \$ 50.00 |
| 7 | Rear bumper clips | 1 | \$ 50.00 | \$ 50.00 30.00 |
| 8 | Rear bumper reverse sensor | 2 | \$ 250.00 | \$ 500.00 200.00 |
| 9 | Rear end panel sealant | 1 | \$ 100.00 | \$ 100.00 40.00 |
| 10 | Rear end panel top garnish clips | 1 | \$ 50.00 | \$ 50.00 30.00 |
| 11 | Rear fender inner trim board clips | 2 | \$ 50.00 | \$ 100.00 |
| 12 | Taillamp seal RH | 2 | \$ 60.00 | \$ 120.00 30.00 |
| 13 | Taillamp clips | 1 | \$ 50.00 | \$ 50.00 20.00 |
| SPECIAL NETT TOTAL : | | | | \$ 1,520.00 |

490.00

| Nos. | LABOUR | S\$ |
|----------------|--------------------------------|-------------------------------|
| 1 | R&R bootlid component | \$ 150.00 80.00 |
| 2 | R&R rear bumper reverse sensor | \$ 100.00 60.00 |
| 3 | Diagnostic & reset fault code | \$ 300.00 |
| 4 | Upholstery | \$ 300.00 |
| 5 | Check wiring | \$ 100.00 50.00 |
| 6 | Panel beating | \$ 1,400.00 800.00 |
| 7 | Rust proofing | \$ 200.00 |
| 8 | Spray painting | \$ 1,400.00 600.00 |
| LABOUR TOTAL : | | \$ 3,950.00 |

Survey 1/9/2021 1130hrs
 Re survey 1/9/2021 1145hrs
 Lump sum repair
 Repair Days 6
 Train in
 Train in

PARTS TOTAL : \$ 7,005.50
 SPECIAL NETT TOTAL : \$ 1,520.00
 LABOUR TOTAL : \$ 3,950.00
 GRAND TOTAL : \$ 12,475.50

Parts 3219.22
 SN 490.00
 Labour 1590.00
 5299.22
 @ 20% 1059.84
 4239.37

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

LS 4200/v Train in
 27/9/2021

(07) Deformed (08) Slashed (09) Buckled (10) Broken (11) Necessary
(12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (✓) (3) Check (✓)
(4) Not Consistent (X)

Vehicle No: SBU 1001G

Rear Portion

| NAC | INC | Item | CON | AC | QTY |
|------|--------|--------------------------------|-----|----|-----|
| 1137 | 993626 | Rear Number Plate | | | |
| 1138 | 993627 | Rear Number Plate Base | | | |
| 1139 | 993630 | Rear Number Plate Garnish | | | |
| 1140 | 993632 | Rear Number Plate Lamp | | | |
| 1141 | 992958 | Rear Bumper | BR | ✓ | |
| 1142 | 993085 | Rear Bumper Upper | | | |
| 1143 | 993017 | Rear Bumper Lower | | | |
| 1144 | 993054 | Rear Bumper Side | | | |
| 1145 | 993103 | Rear Bumper Tow Cover | | | |
| 1146 | 992341 | Rear Bumper Clips | | | |
| 1147 | 992976 | Rear Bumper Bracket | | | |
| 1148 | 993068 | Rear Bumper Side Retainer | NEC | ✓ | 2 |
| 1149 | 993045 | Rear Bumper Reinforcement | DD | ✓ | |
| 1150 | 992970 | Rear Bumper Beam | | | |
| 1151 | 993077 | Rear Bumper Sponge | | | |
| 1152 | 992999 | Rear Bumper Damper | | | |
| 1153 | 993040 | Rear Bumper Protector | | | |
| 1154 | 993036 | Rear Bumper Pad | | | |
| 1155 | 993026 | Rear Bumper Moulding | | | |
| 1156 | 993044 | Rear Bumper Reflector | | | |
| 1157 | 993023 | Rear Bumper Lower Spoiler | | | |
| 1158 | 994023 | Reverse Sensor | | | |
| 1159 | 993327 | Rear End Panel | DD | ✓ | |
| 1160 | 993339 | Rear End Panel Top Garnish | BR | ✓ | |
| 1161 | 993333 | Rear End Panel Inner Trim | | | |
| 1162 | 990333 | Boot Compartment Inner Trim | | | |
| 1163 | 993851 | Rear LH Taillamp | | | |
| 1164 | 993853 | Rear LH Taillamp Garnish | | | |
| 1165 | 993859 | Rear LH Taillamp Panel | | | |
| 1166 | 995116 | Rear RH Taillamp | BR | ✓ | |
| 1167 | 993853 | Rear RH Taillamp Garnish | BR | ✓ | |
| 1168 | 993859 | Rear RH Taillamp Panel | | | |
| 1169 | 993554 | Rear Apron Panel | | | |
| 1170 | 992895 | Bootlid | PD | ✓ | |
| 1171 | 991328 | Bootlid Emblem | NEC | ✓ | 3 |
| 1172 | 990356 | Bootlid Handle | | | |
| 1173 | 995250 | Bootlid Moulding <i>chrome</i> | WT | ✓ | |
| 1174 | 990376 | Bootlid Reflector | | | |
| 1175 | 995222 | Bootlid Lamp LH | BR | ✓ | |
| 1176 | 992899 | Bootlid Lamp RH | WT | ✓ | |
| 1177 | 995243 | Bootlid Lock | | | |
| 1178 | 990377 | Bootlid Rubber | | | |
| 1179 | 990382 | Bootlid Hinge | | | |
| 1180 | 993877 | Bootlid Spoiler | | | |
| 1181 | 994543 | Tailgate | | | |
| 1182 | 991328 | Tailgate Emblem | | | |
| 1183 | 994643 | Tailgate Outer Handle | | | |
| 1184 | 994640 | Tailgate Moulding | | | |
| 1185 | 994545 | Tailgate Garnish | | | |
| 1186 | 994648 | Tailgate Reflector | | | |
| 1187 | 994549 | Tailgate Lamp | | | |
| 1188 | 994646 | Tailgate Protector | | | |
| 1189 | 994676 | Tailgate Wiper Arm | | | |
| 1190 | 994677 | Tailgate Wiper Blade | | | |
| 1191 | 994679 | Tailgate Wiper Nozzle | | | |
| 1192 | 994555 | Tailgate Wiper Motor | | | |
| 1193 | 994602 | Tailgate Glass | | | |
| 1194 | 994606 | Tailgate Glass Rubber | | | |
| 1195 | 994604 | Tailgate Glass Moulding | | | |
| 1196 | 994607 | Tailgate Glass Sealant | | | |
| 1197 | 994629 | Tailgate Lock | | | |
| 1198 | 994651 | Tailgate Rubber | | | |
| 1199 | 994611 | Tailgate Hinge | | | |
| 1200 | 994594 | Tailgate Damper | | | |
| 1201 | 994613 | Tailgate Inner Board | | | |

| NAC | INC | Item | CON | AC | QTY |
|------|--------|--------------------------------|-----|----|-----|
| 1202 | 993784 | Spare Tyre Board | | | |
| 1203 | 994328 | Spare Tyre Panel | | | |
| 1204 | 995065 | Spare Tyre | | | |
| 1205 | 994326 | Spare Tyre Lock Screw | | | |
| 1206 | 993787 | Spare Tyre Cover | | | |
| 1207 | 995323 | Triangle Breakdown Sign | | | |
| 1208 | 990507 | CD Changer Assy | | | |
| 1209 | 990164 | Antenna | | | |
| 1210 | 990534 | Centre Exhaust Pipe Assy | | | |
| 1211 | 990532 | Centre Exhaust Mounting | | | |
| 1212 | 993364 | Rear Exhaust Pipe | | | |
| 1213 | 993357 | Rear Exhaust Chrome Pipe | | | |
| 1214 | 993361 | Rear Exhaust Mounting | | | |
| 1215 | 993358 | Rear Exhaust Heat Shield | | | |
| 1216 | 995223 | Rear LH Chassis Member | | | |
| 1217 | 993165 | Rear RH Chassis Member | | | |
| 1218 | 993436 | Rear LH Fender | | | |
| 1219 | 993449 | Rear LH Fender Protector | | | |
| 1220 | 993420 | Rear LH Fender Inner Panel | | | |
| 1221 | 993431 | Rear LH Fender Inner Trim | | | |
| 1222 | 993415 | Rear LH Fender Inner Garnish | | | |
| 1223 | 993425 | Rear LH Fender Inner Shield | | | |
| 1224 | 993621 | Rear LH Mudflap | | | |
| 1225 | 993933 | Rear LH Wheel Rim | | | |
| 1226 | 994025 | Rear LH Rim Cover | | | |
| 1227 | 995065 | Rear LH Tyre | | | |
| 1228 | 993456 | Rear RH Fender | | | |
| 1229 | 993450 | Rear RH Fender Protector | | | |
| 1230 | 993420 | Rear RH Fender Inner Panel | | | |
| 1231 | 993431 | Rear RH Fender Inner Trim | | | |
| 1232 | 993415 | Rear RH Fender Inner Garnish | | | |
| 1233 | 993425 | Rear RH Fender Inner Shield | | | |
| 1234 | 993622 | Rear RH Mudflap | | | |
| 1235 | 993934 | Rear RH Wheel Rim | | | |
| 1236 | 994025 | Rear RH Rim Cover | | | |
| 1237 | 995065 | Rear RH Tyre | | | |
| 1238 | 995162 | Rear Fender Extension Panel LH | | | |
| 1239 | 993401 | Rear Fender Extension Panel RH | | | |
| 1240 | 993430 | Rear Fender Inner Top Garnish | | | |
| 1241 | 993673 | Rear Fender 1/4 Glass | | | |
| 1242 | 993452 | Rear Fender 1/4 Glass Rubber | | | |
| 1243 | 993453 | Rear Fender 1/4 Glass Sealant | | | |
| 1244 | 993949 | Rear Windscreen Glass | | | |
| 1245 | 993976 | Rear Windscreen Rubber | | | |
| 1246 | 993961 | Rear Windscreen Moulding | | | |
| 1247 | 993955 | Rear Windscreen Sealant | | | |
| 1248 | 994729 | Third Brake Light | | | |
| 1249 | 993385 | Rear Fender Air Grille | | | |
| 1250 | 992167 | Fuel Lid | | | |
| 1251 | 992168 | Fuel Neck | | | |
| 1252 | 992179 | Fuel Tank | | | |
| 1253 | 992184 | Fuel Tank Bracket | | | |
| 1254 | 992191 | Fuel Tank Float | | | |
| 1255 | 990247 | Sticker | | | |

No of Items: 12

Assessor: TCTM

27/9/2021

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------------|--------------------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Singapore NRIC |
| Owner ID: | 183B |
| Vehicle Details | |
| Vehicle No.: | SBU1001G |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 27 Sep 2021 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | TOYOTA COROLLA ALTIS 1.6L CVT |
| Primary Colour: | White |
| Manufacturing Year: | 2015 |
| Engine No.: | 1ZRX551661 |
| Chassis No.: | MR053REH104545390 |
| Maximum Power Output: | 90.0 kW (120 bhp) |
| Open Market Value: | \$19,589.00 |
| Original Registration Date: | 29 Mar 2016 |
| First Registration Date: | 29 Mar 2016 |
| Transfer Count: | 2 |
| Actual ARF Paid: | \$19,589.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 28 Mar 2026 |
| PARF Rebate Amount: | \$13,712.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 28 Mar 2026 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$45,000.00 |
| COE Rebate Amount: | \$20,262.00 |
| Total Rebate Amount: | \$33,974.00 |

The information contained herein is correct as at 27 Sep 2021

OK

MV 48,000/✓
PV 33,974/✓
NV 14,026

Tim Lin
27/9/2021

Used Toyota Cars | Singapore Car Prices & Listing - sgCarMart

**Toyota Corolla Fielder 1.5A X (OPC)**

-

N.A

07-Apr-2016

1,495 cc

-

Stationwagon

SOLD

Normal Plate At Only \$8400 Additional! One Of The Most Spacious Boot Space For Toyota Unit! Designed For All Users Whom Need Space For Deliveries And Pram Etc. Accident Free, Beautiful Interior And Exterior, Flexible Finance Available! High Trade In, A Reliabl...

PREMIUM AD

Posted: 14-Jul-2021 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla

**Toyota Corolla Altis 1.6A Elegance**

\$55,888

\$10,150 /yr

12-Apr-2016

1,598 cc

37,100 km

Sedan

Available

1 Owner! Genuine Low Mileage With Service Records. Owner's 2nd Car. Always Park Under Shelter. Original Paintwork In Showroom Condition. Buy With Peace Of Mind With 1-Year/20,000 Km Warranty On Engine And Gearbox. Full Loan With Attractive Interest Ra...

PREMIUM AD

Posted: 22-Sep-2021 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla

**Toyota Corolla Altis 1.6A**

\$49,800

\$8,800 /yr

14-Apr-2016

1,598 cc

Sedan

Available

Viewing By Appointment.

✓ This car comes with 6-mth sgCarMart Warranty - the best protection for your car. Learn More

350 VR Cars

Posted: 22-Sep-2021 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla

**Toyota Corolla Altis 1.6A Elegance**

\$54,800

\$9,870 /yr

19-Apr-2016

1,598 cc

78,507 km

Sedan

Available

One Of The Most Popular Mid Size Sedans For Your Family! A Vehicle That's Well Known For Its Reliability And Fuel Efficiency! 100% Accident-Free With Low Mileage Done! Meticulously Well Maintained By Previous Owner With No Repairs Needed. STA Evaluation W...

PREMIUM AD

Posted: 21-Sep-2021 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla

**Save on Petrol with OCBC 365 Card!**

Enjoy huge petrol savings of up to 23%, 6% cashback on all day dining and food delivery. Apply now & enjoy the benefits! 1-yr annual fee waiver.

Find out more!

**Toyota Corolla Altis 1.6A Classic**

\$52,555

\$9,540 /yr

22-Apr-2016

1,598 cc

75,984 km

Sedan

Available

Lowest Interest At 1.68%! This Weekend Price Reduce Now! Only 1 Owner. 100% Loan Approve Guaranteed! 1 Year Extended Warranty! Buy With Assurance! Well Maintained And Well Known Model For Fuel Efficiency And Easy Maintenance! A Spacious Leg R...

Car Premium Pte Ltd

Posted: 24-Sep-2021 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla

**Toyota Corolla Altis 1.6A Classic**

\$53,999

\$9,850 /yr

22-Apr-2016

1,598 cc

62,350 km

Sedan

Available

1 Owner, Agent (Borneo) Unit, \$0 Downpayment Drive Away, Low Mileage Usage, Well Taken By Previous Owner, Nice Paintwork, No Repairs Needed, Non PHV Unit, Reliable And Low Maintenance, Accident-Free, Attractive Low-Interest Rate From 1.88%, Free...

Posted: 22-Sep-2021 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla

**Toyota Corolla Altis 1.6A Classic**

\$55,900

\$10,270 /yr

22-Apr-2016

1,598 cc

-

Sedan

Available

Package Cum With Warranty And Free Servicing Included. Very Well Original Condition And Serviced Regularly. High Loan Available. Please Contact Our Sale Consultants For More Details.

Posted: 22-Sep-2021 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla

**Toyota Corolla Altis 1.6A**

\$53,555

\$9,760 /yr

22-Apr-2016

1,598 cc

68,714 km

Sedan

Available

Only 1 Owner. 100% Loan Approve Guaranteed! Highest ARFI 1 Year Extended Warranty! Buy With Assurance! Well Maintained And Well Known Model For Fuel Efficiency And Easy Maintenance! A Spacious Leg Room For All Passengers And Large Boot Space For All...

Car Premium Pte Ltd

Posted: 04-Sep-2021 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla

**Toyota Corolla Altis 1.6A Classic**

-

N.A

22-Apr-2016

1,598 cc

-

Sedan

SOLD

Our Company Makes It Mandatory To Undergoes Through Covid 19 Antigen Rapid Testing Every 2 Weeks To Ensure Full Safety For Our Clients And Staffs. Cheapest In The Market. 1 Careful Owner Only. Reasonable Low Mileage Done At 67213 Km. Must View To...

✓ This car comes with 6-mth sgCarMart Warranty - the best protection for your car. Learn More

PREMIUM AD

Mayfair Motoring

Posted: 27-Aug-2021 Tags: 2016 Toyota Corolla, Toyota Corolla, Toyota, Corolla

**Toyota Corolla Altis 1.6A Classic**

-

N.A

22-Apr-2016

1,598 cc

-

Sedan

SOLD

Our Company Makes It Mandatory For Employees And Management To Undergo A Covid-19 Antigen Rapid Testing Every 2 Weeks. This Ensures The Full Safety Of Our Clients. Door Step Viewing Is Encouraged And Available. One Owner, Most Economical, Fuel Effi...

✓ This car comes with 6-mth sgCarMart Warranty - the best protection for your car. Learn More

PREMIUM AD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|---------------------------------|-------------------------------|
| Date of Submission | 31/08/2021 10:46 (SGT) |
| Date of Accident | 29/08/2021 11:10 (SGT) |
| Exact Location of Accident | Balmoral Plaza, Singapore |
| Additional Location Information | EXIT TOWARDS BUKIT TIMAH ROAD |
| Country/State of Loss | Singapore |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------|
| Vehicle Registration Number | SBU1001G |
|-----------------------------|----------|

INSURED/POLICYHOLDER

| | |
|--------------------------|---------------------------|
| Is company? | No |
| Name Of Registered Owner | ZHANG XINGHUA |
| NRIC No | SXXXX183B |
| Email Address | xinghuazhang667@gmail.com |
| Mobile Phone No | (Phone) +65-96744003 |
| Alternative Phone No | +65-96744003 |

VEHICLE PARTICULARS

| | |
|--|---------------------------|
| Manufacturer | Toyota |
| Model | Corolla |
| Variant | - |
| Exact purpose for which vehicle was being used at time of accident | Private use |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category | Private car |
| Transmission | Auto |
| CC | 1598 |

INSURANCE COMPANY

| | |
|---------------------------|--------------------------------------|
| Name of Insurance Company | AIG Asia Pacific Insurance Pte. Ltd. |
| Type of Coverage | Comprehensive |
| Fleet Policy | No |
| Policy Number | 1900158762-01 |
| Cover Note Number | - |

DRIVER

| | |
|----------------|---------------|
| Name of Driver | ZHANG XINGHUA |
| NRIC No | SXXXX183B |

| | |
|--|--|
| Date Of Birth | 25/10/1978 |
| Occupation | Indoor |
| Date Of Driving Pass | 15/10/2007 |
| Driving experience | 13 YEARS AND 10 MONTHS |
| Gender | Male |
| Mobile Number | (Phone) +65-96744003 |
| Alt. Phone Number | +65-96744003 |
| Email Address | xinghuazhang667@gmail.com |
| Address | BLK 667B JURONG WEST STREET 65 #10-157 |
| Address complement | - |
| Postcode | 642667 |
| Is the driver the policyholder? | Yes |
| If No, Relationship of the Driver with the Insured | - |
| Does Driver Own Other Vehicles? | No |
| Vehicle Registration Number of Other Vehicle Owned by Driver | - |
| Insurance Company of Other Vehicle Owned by Driver | - |

GENERAL INFORMATION OF THE ACCIDENT

| | |
|--------------------------|--------------------------|
| Type of Accident | Collision - Head to Rear |
| Weather Conditions | Clear |
| Road Surface | Dry |

OTHER INFORMATION

| | |
|---|-----|
| Was any foreign vehicle involved in the accident? | No |
| Number of vehicles involved in the accident | 2 |
| Was anybody injured in the Accident? | No |
| Was any injured conveyed to hospital by ambulance? | - |
| Was any other vehicle or property damaged? | Yes |
| Number of Passengers (Including Driver) | 1 |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? | No |

DETAILS OF POLICE ACTION

| | |
|---|----|
| Was the accident reported to the police? | No |
| Was notice of intended Prosecution given? | No |
| If yes, against whom? | - |

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO SKETCH PLAN

ATTACHMENT(S)

| | |
|---|-----|
| Are accident photos available for attachment? | Yes |
| Was there any video captured by Car Camera? | No |
| Was there any audio recorded? | No |

DETAILS OF OTHER VEHICLE PROPERTY 1

| | |
|-----------------------------------|----------------------|
| Vehicle Registration Number | SME1383H |
| Vehicle Manufacturer | - |
| Vehicle Model | - |
| Vehicle Variant | - |
| Vehicle Colour | - |
| Vehicle Category | Private car |
| Name of Driver | TAN PENG CHIANG |
| NRIC No | SXXXX881G |
| Contact Number | (Phone) +65-96541629 |
| Address | - |

Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
 8. Consent under the Personal Data Protection Act (PDPA)
- I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

| | | |
|---|---|--|
| <p><i>Zhang</i></p> <p>Policyholder's Signature / Date & Time</p> | <p><i>Zhang</i></p> <p>Driver's Signature (if driver is not the policyholder) / Date & Time</p> | <p><i>3/08/2021</i></p> <p>Witnessed by Reporting Centre Personnel</p> |
| <p>Sketch Plan</p> <div style="display: flex; align-items: flex-start;"> <div style="margin-right: 20px;"> <p>Exit from BALMORAL Plaza</p> </div> <div> <p>From BALMORAL Plaza TOWARDS To BT Timah Road</p> <p>+ Veh A: SBU 1001 G</p> <p>+ Veh B: SME 1383 H</p> </div> </div> | | |

On 24/08/2021 around 1110 hrs, my vehicle (A) was stationary at the exit of Balmore Plaza towards Enders Tunnel Road. Suddenly vehicle B collided into the rear of my vehicle.

We declare the foregoing particulars are true in every respect

Witnessed by Reporting Centre Personnel